



Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to a penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.							
1. REPORT DATE 2000			3. DATES COVERED				
4. TITLE AND SUBTITLE				5a. CONTRACT NUMBER			
Physical-Habitat a Central Arizona B	nd Geomorphic Dat	a for Selected River	Reaches in	5b. GRANT NUMBER			
Central Arizona D	asiiis, 1995-96			5c. PROGRAM ELEMENT NUMBER			
6. AUTHOR(S)				5d. PROJECT NU	JMBER		
				5e. TASK NUMBER			
				5f. WORK UNIT	NUMBER		
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U.S. Department of the Interior 1849 C Street, NW Washington, DC 20240 8. PERFORMING REPORT NUMBER				G ORGANIZATION ER			
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)			
		11. SPONSOR/M NUMBER(S)	ONITOR'S REPORT				
12. DISTRIBUTION/AVAIL Approved for publ	LABILITY STATEMENT ic release, distributi	on unlimited					
13. SUPPLEMENTARY NO The original docum	otes nent contains color i	mages.					
14. ABSTRACT							
15. SUBJECT TERMS							
16. SECURITY CLASSIFICATION OF: 17. LIMITATION OF: 17. LIMITATION OF: 18. NO.				18. NUMBER	19a. NAME OF		
a. REPORT b. ABSTRACT c. THIS PAGE SAR unclassified unclassified unclassified				OF PAGES 167	RESPONSIBLE PERSON		

Report Documentation Page

Form Approved OMB No. 0704-0188

Physical-Habitat and Geomorphic Data for Selected River Reaches in Central Arizona Basins, 1995–98

By K.M. Beaulieu, J.P. Capesius, and J.B. Gebler

Open-File Report 00—90

NATIONAL WATER-QUALITY ASSESSMENT PROGRAM

U.S. DEPARTMENT OF THE INTERIOR BRUCE BABBITT, Secretary

U.S. GEOLOGICAL SURVEY Charles G. Groat, Director

The use of firm, trade, and brand names in this report is for identification purposes only and does not constitute endorsement by the U.S. Geological Survey.

For additional information write to:

District Chief U.S. Geological Survey Water Resources Division 520 N. Park Avenue, Suite 221 Tucson, AZ 85719–5035 Copies of this report can be purchased from:

U.S. Geological Survey Information Services Box 25286 Federal Center Denver, CO 80225–0046

Information regarding research and data-collection programs of the U.S. Geological Survey is available on the Internet via the World Wide Web. You may connect to the home page for the Arizona District Office using the URL http://az.water.usgs.gov.

FOREWORD

The mission of the U.S. Geological Survey (USGS) is to assess the quantity and quality of the earth resources of the Nation and to provide information that will assist resource managers and policymakers at Federal, State, and local levels in making sound decisions. Assessment of water-quality conditions and trends is an important part of this overall mission.

One of the greatest challenges faced by water-resources scientists is acquiring reliable information that will guide the use and protection of the Nation's water resources. That challenge is being addressed by Federal, State, interstate, and local water-resources agencies and by many academic institutions. These organizations are collecting water-quality data for a host of purposes that include: compliance with permits and water-supply standards; development of remediation plans for a specific contamination problem; operational decisions on industrial, wastewater, or water-supply facilities; and research on factors that affect water quality. An additional need for water-quality information is to provide a basis on which regional and national-level policy decisions can be based. Wise decisions must be based on sound information. As a society we need to know whether certain types of water-quality problems are isolated or ubiquitous, whether there are significant differences in conditions among regions, whether the conditions are changing over time, and why these conditions change from place to place and over time. The information can be used to help determine the efficacy of existing water-quality policies and to help analysts determine the need for and likely consequences of new policies.

To address these needs, the Congress appropriated funds in 1986 for the USGS to begin a pilot program in seven project areas to develop and refine the National Water-Quality Assessment (NAWQA) program. In 1991, the USGS began full implementation of the program. The NAWQA program builds upon an existing base of water-quality studies of the USGS, as well as those of other Federal, State, and local agencies. The objectives of the NAWQA program are to:

- Describe current water-quality conditions for a large part of the Nation's freshwater streams, rivers, and aquifers.
- Describe how water quality is changing over time.
- Improve understanding of the primary natural and human factors that affect water-quality conditions.

This information will help support the development and evaluation of management, regulatory, and monitoring decisions by other Federal, State, and local agencies to protect, use, and enhance water resources.

The goals of the NAWQA program are being achieved through ongoing and proposed investigations of 60 of the Nation's most important river basins and aquifer systems, which are referred to as study units. These study units are distributed throughout the Nation and cover a diversity of hydrogeologic settings. More than two-thirds of the people served by public water-supply systems live within their boundaries.

National synthesis of data analysis, based on aggregation of comparable information obtained from the study units, is a major component of the program. This effort focuses on selected water-quality topics using nationally consistent information. Comparative studies will explain differences and similarities in observed water-quality conditions among study areas and will identify changes and trends and their causes. The first topics addressed by the national synthesis are pesticides, nutrients, volatile organic compounds, and aquatic biology. Discussions on these and other water-quality topics will be published in periodic summaries of the quality of the Nation's ground and surface water as the information becomes available.

This report is an element of the comprehensive body of information developed as part of the NAWQA program. The program depends heavily on the advice, cooperation, and information from many Federal, State, interstate, Tribal, and local agencies and the public. The assistance and suggestions of all are greatly appreciated.

Robert M. Hirsch

Associate Director for Water

Robert M. Hirsch

CONTENTS

	Page
Abstract	1
Introduction	1
Purpose and scope	3
Description of study area	4
Data-collection methods and calculations	4
Physical-habitat and geomorphic data	5
References cited	5
Physical and geomorphic data for selected river segments	7
San Pedro River near Hereford, Arizona	8
San Pedro River near Highway 90, Arizona	20
San Pedro River at Charleston, Arizona	32
Gila River at Kelvin, Arizona	55
Santa Cruz River at Tubac, Arizona	66
Santa Cruz River at Cortaro, Arizona	77
Salt River near Roosevelt, Arizona	88
Verde River above West Clear Creek, near Camp Verde, Arizona	99
West Clear Creek near Camp Verde, Arizona	110
Verde River below Tangle Creek, above Horseshoe Dam, Arizona	133
91st Avenue wastewater-treatment plant outfall near Phoenix, Arizona	144

FIGURES

		Page
1–2.	Maps showing:	
1 2.	Central Arizona Basins study area and physical- and geomorphic-measurement sites	. 2
	2. Location of transects 1–6, reaches A–C, San Pedro River near Hereford, Arizona	
3–8.	Graphs showing:	
	3. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, San Pedro	
	River near Hereford Road, Arizona, based on measurements made December 12, 1996	. 11
	4. Bed-material types at transects 1–6 and average for reach A, San Pedro River near	
	Hereford Road, Arizona, December 12, 1996	. 12
	5. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach B, San Pedro	
	River near Hereford Road, Arizona, based on measurements made December 18, 1996	14
	6. Bed-material at transects 1–6 and average for reach B, San Pedro River near Hereford	
	Road, Arizona, December 18, 1996	15
	7. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach C, San Pedro	. 15
	River near Hereford Road, Arizona, based on measurements made December 19, 1996	17
	8. Bed-material types at transects 1–6 and average for reach C, San Pedro River near	. 1/
	Hereford Road, Arizona, December 19,1996	18
9.	Map showing location of transects 1–6, reaches A–C, San Pedro River near	. 10
9.	Highway 90, Arizona	21
10–15.	Graphs showing:	. 21
10–13.	10. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, San Pedro	
	River near Highway 90, Arizona, based on measurements made December 5, 1996	23
	11. Bed-material types at transects 1–6 and average for reach A, San Pedro River near	. 23
	Highway 90, Arizona, December 5, 1996	. 24
	12. Monthly distribution of solar insolation at transects 1, 5, 6, and midreach, reach B, San Pedro	. 24
	River near Highway 90, Arizona, based on measurements made December 5, 1996	. 26
	13. Bed-material types at transects 1–6 and average for reach B, San Pedro River near	. 20
	Highway 90, Arizona, December 5, 1996	27
	14. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach C, San Pedro	. 21
	River near Highway 90, Arizona, based on measurements made December 6, 1996	. 29
	15. Bed-material types at transects 1–6 and average for reach C, San Pedro River near	. 29
	Highway 90, Arizona, December 6, 1996	20
16	Map showing Location of transects 1–6, reaches A–C, San Pedro River at Charleston, Arizona	
16. 17–28.	Graphs showing:	. 33
17-20.		
	17. Longitudinal profile, reach A, San Pedro River at Charleston, Arizona, January 28	. 34
	and 29, 1998	. 34
	January 28 and 29, 1998. A. Transect A1	. 34
	B. Transect A2	
	C. Transect A4	
	D. Transect A4	
	E. Transect A6	
	F. Transect A6	. 30

FIGURES—Continued Page

	19. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A,	
	San Pedro River at Charleston, Arizona, based on measurements made	
	December 8, 1995	40
	20. Bed-material types at transects 1–6 and average for reach A, San Pedro River at	
	Charleston, Arizona, December 8, 1995	41
	21. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, San Pedro	
	River at Charleston, Arizona, based on measurements made December 8, 1995	43
	22. Bed-material types at transects 1–6 and average for reach A, San Pedro River at Charleston,	
	Arizona, December 8, 1995	44
	23. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach B, San Pedro	
	River at Charleston, Arizona, based on measurements made November 18, 1996	46
	24. Bed-material at transects 1–6 and average for reach B, San Pedro River at Charleston,	
	Arizona, November 18, 1996	47
	25. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach C, San Pedro	
	River at Charleston, Arizona, based on measurements made November 22, 1996	49
	26. Bed-material at transects 1–6 and average for reach C, San Pedro River at Charleston,	
	Arizona, November 22, 1996	50
	27. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, San Pedro	
	River at Charleston, Arizona, based on measurements made November 2, 1997	52
	28. Bed-material types at transects 1–6 and average for reach A, San Pedro River at	
	Charleston, Arizona, November 20, 1997	
29.	Map showing location of transects 1–6, reach A, Gila River at Kelvin, Arizona	56
30–33.	Graphs showing:	
	30. Longitudinal profile, reach A, Gila River at Kelvin, Arizona, November 3 and 4, 1998	
	31. Cross sections of channel, reach A, Gila River at Kelvin, Arizona, November 3 and 4, 1998	59
	32. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A,	
	Gila River at Kelvin, Arizona, based on measurements made November 27, 1995	63
	33. Bed-material types at transects 1–6 and average for reach A, Gila River at Kelvin,	
	Arizona, November 27, 1995	
34.	Map showing location of transects 1–6, reach A, Santa Cruz River at Tubac, Arizona	67
35–39.	Graphs showing:	
	35. Longitudinal profile, reach A, Santa Cruz River at Tubac, Arizona, January 7 and 12, 1998	68
	36. Cross sections of channel, reach A, Santa Cruz River at Tubac, Arizona, January 7	
	and 12, 1998:	
	A. Transect A1	
	B. Transect A2	
	C. Transect A3	
	D. Transect A4	
	E. Transect A5	
	F. Transect A6	70
	37. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A,	
	Santa Cruz River at Tubac, Arizona, based on measurements made	7.4
	January 19, 1996	/4
	38. Bed-material types at transects 1–6 and average for reach A, Santa Cruz River at Tubac,	75
20	· ··, · · · · · · · · · · · · · · · · ·	75
39. 40–43.	Map showing Location of transects 1–6, reach A, Santa Cruz River at Cortaro, Arizona	18
40–43.	Graphs showing: 40. Longitudinal profile reach A Sente Cruz Piver at Cortere Arizone January 26, 1908	70
	40. Longitudinal profile, reach A, Santa Cruz River at Cortaro, Arizona, January 26, 1998	19

	41.	Cross sections of channel, reach A, Santa Cruz River at Cortaro, Arizona,	
		January 26, 1998. A. Transect A1	70
		B. Transect A2	
		C. Transect A3	
		D. Transect A4	
		E. Transect A5	
		F. Transect A6	
	12	Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A,	01
	42.	· · · · · · · · · · · · · · · · · · ·	
		Santa Cruz River at Cortaro, Arizona, based on measurements made January 23, 1996	05
	12	Bed-material types at transects 1–6 and average for reach A, Santa Cruz River at Cortaro,	63
	43.	• • • • • • • • • • • • • • • • • • • •	06
4.4	M	Arizona, January 23, 1996	
44.		ap showing location of transects 1–6, reach A, Salt River near Roosevelt, Arizona	89
45–48.		raphs showing:	00
		Longitudinal profile, reach A, Salt River near Roosevelt, Arizona, July 27 and 28, 1998	90
	46.	Cross sections of channel, reach A, Salt River near Roosevelt, Arizona,	
		July 27 and 28, 1998.	0.0
		A. Transect A1	
		B. Transect A2	
		C. Transect A3	
		D. Transect A4	
		E. Transect A5	
		F. Transect A6	92
	47.	Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, Salt River near Roosevelt, Arizona, based on measurements made December 13, 1995	06
	10	Bed-material types at transects 1–6 and average by reach A, Salt River near Roosevelt,	90
	40.		
49.	M	Arizona, December 13, 1995. 97	
49.		ap showing location of transects 1–6, reach A, Verde River above West Clear Creek, ar Camp Verde, Arizona	100
50–53.		1	100
30–33.		raphs showing:	
	30.	Longitudinal profile, reach A, Verde River above West Clear Creek, near Camp Verde, Arizon	ıa,
	<i>5</i> 1	December 1 and 5, 1997. Local datum established using arbitrary elevation. 101	
	31.	Cross sections of channel, reach A, Verde River above West Clear Creek, near	
		Camp Verde, Arizona, December 1 and 5, 1997.	100
		A. Transect A1	
		B. Transect A2	
		C. Transect A3	
		D. Transect A4	
		E. Transect A5	
	5 0	F. Transect A6	102
	52.	Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A,	
		Verde River above West Clear Creek, near Camp Verde, Arizona, based on	107
		measurements made October 24, 1995	107
	53.	Bed-material types at transects 1–6 and average for reach A, Verde River above	400
		West Clear Creek, near Camp Verde, Arizona, October 24, 1995	108
54.		ap showing location of transects 1–6, reaches A–C, West Clear Creek near	
	Ca	ımp Verde, Arizona	111

55–56.	Graphs showing:	
	55. Longitudinal profile, reach A, West Clear Creek near Camp Verde, Arizona,	
	December 3 and 4, 1997	112
	56. Cross sections of channel, reach A, West Clear Creek, near Camp Verde, Arizona,	
	December 3 and 5, 1997.	
	A. Transect A1	
	B. Transect A2	
	C. Transect A3	
	D. Transect A4	
	E. Transect A5	
	F. Transect A6	114
	57. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A,	
	West Clear Creek near Camp Verde, Arizona, based on measurements made	
	October 11, 1995	118
	58. Bed-material types at transects 1–6 and average for reach A, West Clear Creek near	
	Camp Verde, Arizona, October 11, 1995	119
	59. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A,	
	West Clear Creek near Camp Verde, Arizona, based on measurements made	
	October 24, 1996	121
	60. Bed-material types at transects 1–6 and average for reach A, West Clear Creek near	
	Camp Verde, Arizona, October 24, 1996	122
	61. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach B,	
	West Clear Creek near Camp Verde, Arizona, based on measurements made	
	October 31, 1996	123
	62. Bed-material types at transects 1–6 and average for reach B, West Clear Creek near	
	Camp Verde, Arizona, October 31, 1996	124
	63. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach C,	
	West Clear Creek near Camp Verde, Arizona, based on measurements made	
	November 6, 1996	127
	64. Bed-material types at transects 1–6 and average for reach C, West Clear Creek near	
	Camp Verde, Arizona, November 6, 1996	128
	65. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A,	
	West Clear Creek near Camp Verde, Arizona, based on measurements made	
	November 6, 1997	130
	66. Bed-material types at transects 1–6 and average for reach A, West Clear Creek	
	near Camp Verde, Arizona, November 6, 1997	131
67.	Map showing location of transects 1–6, reach A, Verde River below Tangle Creek,	
	above Horseshoe Dam, Arizona	134
68–71.	Graphs showing:	-
	68. Longitudinal profile, reach A, Verde River below Tangle Creek, above Horseshoe Dam,	
	Arizona, July 29, 1998. Local datum established using arbitrary elevation	135
	69. Cross sections of channel, reach A, Verde River below Tangle Creek, above	
	Horseshoe Dam, Arizona, July 29, 1998.	
	A. Transect A1	135
	B. Transect A2	
	C. Transect A3	
	D. Transect A4	
	E. Transect A5	
	F. Transect A6	

FIGURES—Continued Page

TIGOTILO	, 0	ontinucu	ragi
	70.	Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, Verde River below Tangle Creek, above Horseshoe Dam, Arizona, based on measurements made January 31, 1996	1./1
	71	Bed-material types at transects 1–6 and average for reach A, Verde River below	171
	/1.	Tangle Creek, above Horseshoe Dam, Arizona, January 31, 1996	1/12
72.	M	up showing location of transects 1–6, reach A, 91st Avenue wastewater-treatment plant	172
12.		fall near Phoenix, Arizonafall near Phoenix, Arizona	1/15
73–76.		aphs showing:	173
73 70.		Longitudinal profile, reach A, 91st Avenue wastewater-treatment plant outfall near Phoenix, Arizona, October 21 and 22, 1997	1/16
	74.	Cross sections of channel, reach A, 91st Avenue wastewater-treatment plant outfall near Phoenix, Arizona, October 21 and 22, 1997.	140
		A. Transect A1	146
		B. Transect A2	
		C. Transect A3	
		D. Transect A4	
		E. Transect A5	
		F. Transect A6	
	75.	Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, 91st Avenue wastewater-treatment plant outfall near Phoenix, Arizona, based	
		on measurements made November 29, 1995	152
	76.	Bed-material types at transects 1–6 and average for reach A, 91st Avenue	
		wastewater-treatment plant outfall near Phoenix, Arizona,	
		November 29, 1995	153

TABLES

		Page
1.	Summary of measurement sites for Central Arizona Basins study area	3
2.	Size classes used to quantify streambed substrate in the Wolman Pebble Count procedure	5
3.	Habitat characteristics of reach A, San Pedro River near Hereford Road, Arizona,	
	December 12, 1996	10
4.	Density and dominance of woody vegetation for reach A, San Pedro River near	
	Hereford Road, Arizona, December 12, 1996	13
5.	Habitat characteristics of reach B, San Pedro River near Hereford Road, Arizona,	
	December 18, 1996	13
6.	Density and dominance of woody vegetation for reach B, San Pedro River near	
	Hereford Road, Arizona, December 18, 1996	16
7.	Habitat characteristics of reach C, San Pedro River near Hereford Road, Arizona,	
	December 17, 1996	16
8.	Density and dominance of woody vegetation for reach C, San Pedro River near	
	Hereford Road, Arizona, December 17, 1996	19
9.	Habitat characteristics of reach A, San Pedro River near Highway 90, Arizona,	
	December 5, 1996	22
10.	Density and dominance of woody vegetation for reach A, San Pedro River near	
	Highway 90, Arizona, December 5, 1996	25
11.	Habitat characteristics of reach B, San Pedro River near Highway 90, Arizona,	
	December 5, 1996	25
12.	Density and dominance of woody vegetation for reach B, San Pedro River at	
	Highway 90, Arizona, December 5, 1996	28
13.	Habitat characteristics of reach C, San Pedro River near Highway 90, Arizona,	
	December 6, 1996	28
14.	Density and dominance of woody vegetation for reach C, San Pedro River near	
	Highway 90, Arizona, December 6, 1996	31
15.	Cross-sectional survey data for reach A, San Pedro River at Charleston, Arizona,	
	January 28 and 29, 1998	35
16.	Description and location of semipermanent monuments for reach A, San Pedro River	
	at Charleston, Arizona, January 28 and 29, 1998	39
17.	Habitat characteristics of reach A, San Pedro River at Charleston, Arizona,	
	December 8, 1995	39
18.	Density and dominance of woody vegetation for reach A, San Pedro River at	
	Charleston, Arizona, December 8,1995	42
19.	Habitat characteristics of reach A, San Pedro River at Charleston, Arizona,	
	November 13, 1996	42
20.	Density and dominance of woody vegetation for reach A, San Pedro River at	
	Charleston, Arizona, November 13, 1996	45
21.	Habitat characteristics of reach B, San Pedro River at Charleston, Arizona,	
	November 18, 1996	45
22.	Density and dominance of woody vegetation for reach B, San Pedro River at	
	Charleston, Arizona, November 18, 1996	48

TABLES-	—Continued	Page
23.	Habitat characteristics of reach C, San Pedro River at Charleston, Arizona,	
2.4	November 22, 1996	48
24.	Density and dominance of woody vegetation for reach C, San Pedro River at	<i>7</i> 1
25.	Charleston, Arizona, November 22, 1996	31
23.	November 20, 1997	51
26.	Density and dominance of woody vegetation for reach A, San Pedro River at	31
20.	Charleston, Arizona, November 20, 1997	54
27.	Cross-sectional survey data for reach A, Gila River at Kelvin, Arizona,	5-
	November 3 and 4, 1998	58
28.	Description and location of semipermanent monuments for reach A, Gila River at	
	Kelvin, Arizona, November 3 and 4, 1998	62
29.	Habitat characteristics of reach A, Gila River at Kelvin, Arizona, November 27, 1995	62
30.	Density and dominance of woody vegetation for reach A, Gila River at Kelvin,	
	Arizona, November 27, 1995	65
31.	Cross-sectional survey data for reach A, Santa Cruz River at Tubac, Arizona,	
	January 7 and 12, 1998	69
32.	Description and location of semipermanent monuments for reach A, Santa Cruz River	
	at Tubac, Arizona, January 12, 1998	73
33.	Habitat characteristics of reach A, Santa Cruz River at Tubac, Arizona,	5 2
2.4	January 19, 1996.	
34.	Density and dominance of woody vegetation for reach A, Santa Cruz River at Tubac,	76
35.	Arizona, January 19, 1996	/6
33.	January 26, 1998	80
36.	Description and location of semipermanent monuments for reach A, Santa Cruz River	60
50.	at Cortaro, Arizona, January 26, 1996	84
37.	Habitat characteristics of reach A, Santa Cruz River at Cortaro, Arizona,	
57.	January 23, 1996.	84
38.	Density and dominance of woody vegetation for reach A, Santa Cruz River at	
	Cortaro, Arizona, January 23, 1996	87
39.	Cross-sectional survey data for reach A, Salt River near Roosevelt, Arizona,	
	July 27 and 28, 1998	91
40.	Description and location of semipermanent monuments for reach A, Salt River	
	near Roosevelt, Arizona, July 27 and 28, 1998	95
41.	Habitat characteristics of reach A, Salt River near Roosevelt, Arizona,	
	December 13, 1995	95
42.	Density and dominance of woody vegetation for reach A, Salt River near Roosevelt,	
	Arizona, December 13, 1995	98
43.	Cross-sectional survey data for reach A, Verde River above West Clear Creek, near	40=
4.4	Camp Verde, Arizona, December 1 and 5, 1997	105
44.	Description and location of semipermanent monuments for reach A, Verde River	106
15	above West Clear Creek near Camp Verde, Arizona, December 1 and 5, 1997	106
45.	Habitat characteristics of reach A, Verde River above West Clear Creek, near	104
46.	Camp Verde, Arizona, October 24, 1995 Density and dominance of woody vegetation for reach A, Verde River above	100
+0.	West Clear Creek, near Camp Verde, Arizona, October 24, 1995	109
	11 COR \$ 10 COR \$ 10 COR 10 COR \$ 20 COR 1	107

TABLES—Continued	Pag	је

47.	Cross-sectional survey data for reach A, West Clear Creek near Camp Verde,	
	Arizona, December 3 and 4, 1997	113
48.	Description and location of semipermanent monuments for reach A, West Clear Creek	
	near Camp Verde, Arizona, December 3 and 4, 1997	117
49.	Habitat characteristics of reach A, West Clear Creek near Camp Verde, Arizona,	
	October 11, 1995	117
50.	Density and dominance of woody vegetation for reach A, West Clear Creek near	
	Camp Verde, Arizona, October 11, 1995	120
51.	Habitat characteristics of reach A, West Clear Creek near Camp Verde, Arizona,	
	October 24, 1996	120
52.	Density and dominance of woody vegetation for reach B, West Clear Creek near	105
5 0	Camp Verde, Arizona, October 24, 1996	125
53.	Habitat characteristics of reach B, West Clear Creek near Camp Verde, Arizona,	105
~ 4	October 31, 1996	125
54.	Density and dominance of woody vegetation for reach C, West Clear Creek near	126
	Camp Verde, Arizona, October 31, 1996	126
55.	Habitat characteristics of reach C, West Clear Creek near Camp Verde, Arizona,	106
~ ~	November 6, 1996	126
56.	Density and dominance of woody vegetation for reach C, West Clear Creek near	120
-7	Camp Verde, Arizona, November 6, 1996	129
57.	Habitat characteristics of reach A, West Clear Creek near Camp Verde, Arizona,	120
7 0	November 6, 1997	129
58.	Density and dominance of woody vegetation for reach A, West Clear Creek near	122
50	Camp Verde, Arizona, November 6, 1997	132
59.	Cross-sectional survey data for reach A, Verde River below Tangle Creek, above	126
60	Horseshoe Dam, Arizona, July 29, 1998.	136
60.	Description and location of semipermanent monuments for reach A, Verde River	140
<i>c</i> 1	below Tangle Creek, above Horseshoe Dam, Arizona, July 29, 1998	140
61.	Habitat characteristics of reach A, Verde River below Tangle Creek, above Horseshoe Dam, Arizona, January 31, 1996	140
62.	Density and dominance of woody vegetation for reach A, Verde River below	140
02.		1./2
63.	Tangle Creek, above Horseshoe Dam, Arizona, January 31, 1996	143
03.	Cross-sectional survey data for reach A, 91st Avenue wastewater-treatment plant outfall near Phoenix, Arizona, October 21 and 22, 1997	1.47
64.	Description and location of semipermanent monuments for reach A, 91st Avenue	147
04.	wastewater-treatment plant outfall, near Phoenix, Arizona,	
	October 21 and 22, 1997	151
65.	Habitat characteristics of reach A, 91st Avenue wastewater-treatment plant outfall	131
05.	near Phoenix, Arizona, November 29, 1995	151
66.	Density and dominance of woody vegetation for reach A, 91st Avenue wastewater-	131
00.	treatment plant outfall near Phoenix, Arizona, November 29, 1995	151
	treatment plant outlan flear flocing, Amzolia, November 29, 1993	134

Physical-Habitat and Geomorphic Data for Selected River Reaches in Central Arizona Basins, 1995–98

By K.M. Beaulieu, J.P. Capesius, and J.B. Gebler

Abstract

This report presents data from physical-habitat and geomorphic measurements that were made at 11 stream reaches in the Central Arizona Basins study area of the U.S. Geological Survey's National Water-Quality Assessment program from 1995 to 1998. Measurements of water velocity and depth, particle size of bed material, embeddedness of substrate, stream aspect, and solar contribution were made at each reach. In addition, the extent and type of dominant riparian vegetation along each reach were characterized. To maintain nationwide consistency, data-collection methods were based on protocols developed by the National Water-Quality Assessment program for the assessment of stream habitat.

Measurements were made at a single reach, designated as reach A, at nine sites (termed basic fixed sites) between October 1995 and January 1996. Measurements were made at three reaches, designated as reaches A, B, and C, at two of these sites (West Clear Creek near Camp Verde and San Pedro River near Charleston) between October and December 1996. In addition, measurements were made at three reaches at two other sites on the San Pedro River in December 1996. In October and November 1997, measurements were made at reach A of West Clear Creek near Camp Verde and reach A of the San Pedro River near Charleston. Cross sections and longitudinal profiles were surveyed on the nine basic fixed sites in late 1997 and in 1998.

INTRODUCTION

In 1991, the U.S. Geological Survey implemented the National Water-Quality Assessment (NAWQA) program. The NAWQA program was designed to assess the status and trends of the Nation's water quality and to develop an understanding of the major factors that affect water-quality conditions (Hirsch and others, 1988; Leahy and others, 1990). Program goals are addressed through the integration of physical, chemical, and biological data from 59 study areas. The program will provide a baseline of information for use by policy makers and managers at National, State, and local levels. In 1994, data collection and analysis began in the Central Arizona Basins (CAZB) NAWQA study area (fig. 1).

Ecological assessment, which includes measurements of physical-habitat and geomorphic characteristics, is one aspect of the multidisciplinary NAWQA program. Measurements of riparian and instream characteristics provide information for interpreting water-quality conditions, identifying physical factors critical to biological communities, and yielding an understanding of species distributions relative to habitat characteristics. These data can be used for assessments of long-term trends and changes in biological communities and habitat characteristics that may be caused by changes in physical and chemical constituents, landscape features, and human activities (Gurtz, 1994). The data that are presented in this report were collected with the cooperation of landowners who granted access to the sites.




Figure 1. Central Arizona Basins study area and physical- and geomorphic-measurement sites.

Purpose and Scope

This report describes and summarizes data from physical-habitat and geomorphic measurements made between 1995 and 1998 at 11 sites in the study area (fig. 1 and table 1). Measurements of water velocity and depth, bed-material type and sizes, embeddedness of substrate, stream aspect, and solar contribution were made at each reach. In addition, the extent and type of dominant riparian vegetation along each reach were characterized. Measurements were made at nine basic

fixed sites between October 1995 and January 1996. Measurements were made at two of these basic fixed sites (San Pedro River near Charleston and West Clear Creek near Camp Verde) for 3 consecutive years. Measurements were made at multiple reaches at these two sites and at two additional sites on the San Pedro River (San Pedro River near Hereford Road and San Pedro River near Highway 90) in late 1996. Cross-sectional and longitudinal surveys were completed on the nine basic fixed sites during late 1997 through 1998.

Summary of measurement sites for Central Arizona Basins study area Table 1.

< ·	less	than	ĺ

Site number (see fig. 1)	Site name	Station-identification number	Latitude	Longitude	Basin name	Drainage area, in square kilometers
1	San Pedro River near Hereford Road ¹	312621110062601	31°26'21"	110°06'26"	Upper San Pedro River	•
1					11	2,400
2	San Pedro River near Highway 90 ¹	313256110080701	31°32'56"	110°08'07"	Upper San Pedro River	2,819
3	San Pedro River at Charleston ^{1,2}	09471000	31°37'33"	110°10'26"	Upper San Pedro River	3,257
4	Gila River at Kelvin ²	09474000	33°06'10"	110°58'33"	Middle Gila River	46,648
5	Santa Cruz River at Tubac ^{1,2}	09481740	31°36'46"	111°02'27"	Upper Santa Cruz River	3,131
6	Santa Cruz River at Cortaro ^{1,2}	09486500	32°21'04"	111°05'38"	Upper Santa Cruz River	9,073
7	Salt River near Roosevelt ²	09498500	33°37'10"	110°55'15"	Salt River	11,153
8	Verde River above West Clear Creek near Camp Verde ²	09505570	34°30'20"	111°50'05"	Verde River	12,173
9	West Clear Creek near Camp Verde ²	09505800	34°32'19"	111°41'36"	Verde River	624
10	Verde River below Tangle Creek above Horseshoe Dam ²	09508500	34°04'23"	111°42'56"	Verde River	15,172
11	91st Avenue wastewater-treatment plant outfall near Phoenix ²	09512407	33°23'22"	112°15'13"	Salt River	(3)

Site					Lar	nd use, in perce	nt ⁵	
number (see fig. 1)	Ecological design	Physiographic province 4	Gaging station	Urban	Agriculture	Rangeland	Forest	Other
1	Multiple reach/single year	Basin and Range Lowlands	No	4	5	65	5	21
2	Multiple reach/single year	Basin and Range Lowlands	No	3	3	68	25	1
3	Multiple reach/multiple year	Basin and Range Lowlands	Yes	3	2	76	18	1
4	Single reach/single year	Basin and Range Lowlands	Yes	1	1	84	13	1
5	Single reach/single year	Basin and Range Lowlands	Yes	1	1	55	42	1
6	Single reach/single year	Basin and Range Lowlands	Yes	16	2	59	21	2
7	Single reach/single year	Central Highlands	Yes	1	0	16	83	0
8	Single reach/single year	Central Highlands	No	2	5	32	59	2
9	Multiple reach/multiple year	Central Highlands	Yes	0	0	21	79	0
10	Single reach/single year	Central Highlands	Yes	2	4	33	60	1
11	Single reach/single year	Basin and Range Lowlands	No	(3)	(3)	(3)	(3)	(3)

¹Land-use information not available for the parts of the study area in Mexico. Land-use percentages are for the part of the study area in United States only. ²Basic fixed site.

³Not applicable.

⁵Anderson and others (1976). Urban data for 1990, unpublished, from Maricopa Association of Governments, Pima County, and University of Arizona.

Description of Study Area

The CAZB study unit encompasses 89,900 km² including 2,850 km² in Mexico (**fig. 1**). Five major river systems, the Gila, Salt, Verde, Santa Cruz, and San Pedro, are included in the study area. The climate of the study area is arid to semiarid and has an average precipitation ranging from 15 to 25 cm/yr in the Basin and Range Lowlands and 64 to 102 cm/yr in the Central Highlands (Sellers and Hill, 1974; U.S. Geological Survey, 1969). The population in the study area exceeds 3.1 million people; about 80 percent reside in the Phoenix and Tucson metropolitan areas (Cordy and others, 1998). The environmental setting of the study area is described in detail by Cordy and others (1998).

DATA-COLLECTION METHODS AND CALCULATIONS

Data collection included measurements of instream characteristics, solar contribution to the system, and identification of riparian vegetation. The methods used to measure physical-habitat and geomorphic characteristics of selected sites in the CAZB are described in Meador and others (1993) as part of the reach-level characterization.

Eleven sites were selected for measuring geomorphic and physical-habitat attributes (fig. 1; table 1). At each site, a reach was selected based primarily on the presence of multiple (two or more) major fluvial geomorphic features, such as riffles, runs, or pools. Reach lengths ranged from 121 to 610 m, and the typical length was about 200 to 300 m. Six transects, each oriented perpendicularly to the stream channel and marked by semi-permanent monuments, were selected at each reach to best characterize the occurrence and extent of the major geomorphic features within the reach. At the nine basic fixed sites, cross sections of the stream and riparian zone were surveyed at all transects using either a total station system or a surveying level with surveying rod. Elevation was established by reference to either a local streamflow-gaging station or benchmarks. The length of each transect was measured using a calibrated tape. Longitudinal profiles of the stream channel were constructed using the depth of the thalweg at each transect and the surveyed distance between transects (Harrelson and others, 1994).

Instream measurements were made at every transect. Velocity measurements were made at the thalweg and at least two other points along the transect. Dominant and subdominant substrate or bed-material types were determined at each of the three points. Embeddedness was determined by a categorical rating of the percentage of surface area of particles (gravel, cobble, and boulder) covered by fine sediment.

At each transect, a clinometer was used to determine the extent of canopy openness above midchannel, and a spherical densiometer (Platts and others, 1987) was used to estimate the relative density of riparian vegetation. A Solar Pathfinder (Platts and others, 1987) was used to estimate the amount of incident solar radiation striking the stream. This device is calibrated so that a single measurement is sufficient to provide estimates of solar insolation at different times of the year (Platts and others, 1987). In general, Solar Pathfinder measurements were taken at midchannel at the downstream most and upstream most transects (transects 1 and 6, respectively) and at a point, referred to as midreach, approximately at the midpoint between transects 3 and 4. In a few cases, an island in the stream channel intersected a transect used for Solar Pathfinder measurements. In such cases, two Solar Pathfinder measurements were taken, each at the midpoint of each channel. In one instance (San Pedro River near Highway 90, reach B), a Solar Pathfinder measurement was taken at an additional transect because it was deemed that the extra measurement would increase the representativeness of solar insolation for the reach. The aspect, or compass bearing, corrected for magnetic declination, was determined for the direction of downstream flow at the midpoint of each transect.

To determine bed-material type and sizes, pebble counts were made at all six transects of each reach using a modified Wolman method (Wolman, 1954; Harrelson and others, 1994). Starting at the left edge of water, the investigator took a step, picked up the particle at the toe of his/her boot, and measured the intermediate axis. Particles less than 0.5 cm were identified by texture. This procedure was repeated until the right edge of water was reached (table 2). Consequently, the number of particles measured at each transect varied depending on the width of the wetted channel. These data are represented graphically as percentages for each transect. The average for a reach was determined as the number of particles in a size-class category divided by the total number of particles measured for the reach.

Table 2 Size classes used to quantify streambed substrate in the Wolman Pebble Count procedure [Categories modified from classes of Wentworth (1922). >, greater than; <, less than]

Particle classes	Size, in millimeters	Particle classes	Size, in millimeters
Boulder	>256	Gravel	5 to <16
Cobble	64 to<256	Sand	.06 to <5
Pebble	16 to <64	Silt	.004 to <.06

The point-centered quarter method was used to evaluate density and dominance of woody vegetation (Mueller-Dombois and Ellenberg, 1974). Twelve points in each reach—one point on each bank for each transect—were defined by the intersection of the transect and a line perpendicular to the transect at the top of the bank. From each point, four quadrats were established by the same intersecting lines. In each quadrat, the closest individual woody plant was identified, and the diameter of the plant at breast height and its distance from the point were measured.

Four measures—mean basal area, dominance, absolute frequency, and relative density—were computed for each species to characterize the community of riparian woody vegetation. For each species, basal area for each individual was computed by dividing the diameter at breast height by two (to obtain the radius), squaring that value, and multiplying by pi (truncated at five places past the decimal). Mean basal area for each species was obtained by summing the result for each individual and dividing by the total number of individuals of that species. Dominance was computed by dividing the mean basal area of a particular species by the number of trees of that species in 100 m². In order to compute dominance, values for total distance and mean distance from the measurement point and the number of trees of all species in 100 m², were first obtained. Dominance for a particular species was then determined by multiplying the proportion of that species by the total number of trees of all species in 100 m² to compute the number of that species in 100 m². This value was then multiplied by the mean basal area for the species, which gives dominance (Mueller-Dombois and Ellenberg, 1974).

Absolute frequency for each species was determined by dividing the number of points with which the species was associated by the total number of points. For example, if an individual of a particular species was found in one or more quadrats for 3 of the

12 points, the absolute frequency of that species was 25 percent. More than one individual of a given species associated with a point, such as would be the case if the species was found in more than one quadrat for that point, does not increase the absolute frequency of the plant. Relative density was computed by dividing the number of individuals of a given species by the total number of individuals of all species.

PHYSICAL-HABITAT AND GEOMORPHIC DATA

Physical-habitat and geomorphic data are presented in tabular and graphical formats by reach for each site in downstream order. A map showing the approximate location of the site and transects is given for each site. For basic fixed sites, cross-sectional and longitudinal-survey information is then presented. A table presenting habitat characteristics follows for all sites. Graphs of solar insolation and bed-material types appear and are followed by a table that contains measures of woody vegetation.

REFERENCES CITED

Anderson, J.R., Hardy, E.E., Road, J.T., and Witmer, R.E., 1976, A land use and land cover classification system for use with remote sensor data: U.S. Geological Survey Professional Paper 964, 28 p.


Cordy, G.E., Rees, J.A., Edmonds, R.J., Gebler, J.B., Wirt, Laurie, Gellenbeck, D.J., and Anning, D.W., 1998, Water-quality assessment of the Central Arizona Basins, Arizona and northern Mexico— Environmental setting and overview of water quality: U.S. Geological Survey Water-Resources Investigations Report 98-4097, 71 p.

Fenneman, N.M., 1931, Physiography of Western United States: New York, McGraw-Hill, 534 p.

- Gurtz, M.E., 1994, Design of biological components of the National Water-Quality Assessment (NAWQA) program, *in* Loeb, S.L., and Spacie, A., eds., Biological monitoring of aquatic systems: Boca Raton, Florida, Lewis Publishers, chap. 15, p. 323–354.
- Harrelson, C.C., Rawlings, C.L., and Potyondy, J.P., 1994, Stream channel reference sites—An illustrated guide to field techniques: U.S. Forest Service General Technical Report RM–245, 61 p.
- Hirsch, R.M., Alley, W.M., and Wilber, W.G., 1988, Concepts for a National Water-Quality Assessment program: U.S. Geological Survey Circular 1021, 42 p.
- Leahy, P.P., Rosenshein, J.S., and Knopman, D.S., 1990, Implementation plan for the National Water-Quality Assessment program: U.S. Geological Survey Open-File Report 90–174, 10 p.
- Leopold, L.B., Wolman, M.G., and Miller, J.P., 1964, Fluvial processes in geomorphology: San Francisco, California, W.H. Freeman, 522 p.
- Meador, M.R., Hupp, C.L., Cuffney, T.F., and Gurtz, M.E., 1993, Methods for characterizing stream habitat as part of the National Water-Quality Assessment program: U.S. Geological Survey Open-File Report 93–408, 48 p.

- Mueller-Dombois, Dieter, and Ellenberg, Heinz, 1974, Aims and methods of vegetation ecology: New York, John Wiley and Sons, 547 p.
- Platts, W.S., Armour, Carl, Booth, G.D., Bryant, Mason, Bufford, J.L., Cuplin, Paul, Jensen, Sherman, Lienkaemper, G.W., Minshall, G.W, Monsen, S.B., Nelson, R.L., Sedell, J.R., and Tuhy, J.S., 1987, Methods for evaluating riparian habitats with applications to management: Ogden, Utah, U.S. Forest Service, General Technical Report INT–221, 177 p.
- Sellers, W.D., and Hill, R.H., eds., 1974, Arizona climate, 1931–1972: Tucson, Arizona, University of Arizona Press, 616 p.
- U.S. Geological Survey, 1969, Annual report of ground water in Arizona, spring 1967 to spring 1968: Phoenix, Arizona State Land Department Water-Resources Report 38, 54 p.
- Wentworth, C.K., 1922, A method for measuring and plotting the shapes of pebbles: U.S. Geological Survey Bulletin 730–C, p. 91–114.
- Wolman, M.G., 1954, A method of sampling coarse riverbed material: Washington, D.C., American Geophysical Union, Transactions, v. 35, no. 6, p. 951–956.








Figure 2. Location of transects 1–6, reaches A–C, San Pedro River near Hereford, Arizona.

Table 3. Habitat characteristics of reach A, San Pedro River near Hereford Road, Arizona, December 12, 1996

[Embeddedness categories: 0, no gravel, cobbles, or boulders present; 3, 26 to 50 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment. Dashes indicate no data. <, less than]

		Canopy			Velocity		Sub		
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness
				Transe	ect 1 (Riffle)				
1.7	340	89	6	0.6	0.11	0.24	Gravel	Cobble	5
				1.3	1.22	.68	Cobble	Gravel	3
				1.5	.16	.71	Gravel	Cobble	5
				Transe	ect 2 (Pool)				
8.0	348	28	68	2.1	1.26	.08	Sand	Silt	0
				4.2	.23	.07	Sand	Silt	0
				6.1	.20	.06	Silt	Sand	0
				Transe	ect 3 (Pool)				
9.1	341	4	82	1.0	¹ .57	.19	Sand	Silt	0
				3.7	.43	<.01	Silt	Sand	0
				6.4	.56	.01	Silt	Sand	0
				Trans	ect 4 (Run)				
5.1	6	25	56	1.4	.13	.06	Sand	Silt	0
				2.7	.17	.15	Sand	Silt	0
				4.1	1.30	.16	Sand	Silt	0
				Trans	ect 5 (Run)				
3.9	355	38	34	1.2	.06	.02	Sand	Gravel	5
				2.4	.08	.16	Sand	Gravel	5
				3.6	1.23	.44	Sand	Gravel	5
				Transe	ect 6 (Run)				
6.2	354	78	25	1.4	.12	.17	Sand	Silt	0
				2.9	¹ .18	.12	Sand	Gravel	5
				4.6	.16	.12			

¹Thalweg.




Figure 3. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, San Pedro River near Hereford Road, Arizona, based on measurements made December 12, 1996.




Figure 4. Bed-material types at transects 1–6 and average for reach A, San Pedro River near Hereford Road, Arizona, December 12, 1996.

Density and dominance of woody vegetation for reach A, San Pedro River near Hereford Road, Arizona, December 12, 1996 [Length of reach, 233 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Fremont cottonwood (Populus fremontii)	369	236	42	20
Mesquite (Prosopis sp.)	204	65	25	10
Willow (Salix sp.)	202	452	92	70

Habitat characteristics of reach B, San Pedro River near Hereford Road, Arizona, December 18, 1996 Table 5.

[Embeddedness categories: 0, no gravel, cobbles, or boulders present; 2, 51 to 75 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment. NA, not applicable; <, less than]

		Can	юру		Velocity		Su	bstrate	
Stream width, in meters	Aspect, in degrees	Angle, in degrees	Density, in percent	Distance from left bank, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness
				Trans	sect 1 (Riffle)				
5.0	347	59	35	1.5	10.13	0.52	Gravel	Sand	5
				2.7	.09	.02	Gravel	Sand	5
				4.8	.08	.87	Gravel	Sand	5
				Trans	sect 2 (Riffle)				
15.5	352	82	46	.9	1.18	.13	Sand	Silt	0
				5.0	.07	<.01	Sand	Silt	0
				1.5	.8	<.01	Sand	Silt	0
				Tran	nsect 3 (Run)				
7.6	354	77	7	2.0	.24	<.01	Gravel	Sand	5
				4.0	.27	.04	Gravel	Sand	5
				6.0	1.30	.02	Sand	Silt	0
				Tran	nsect 4 (Pool)				
12.4	2	38	63	3.7	1.98	.02	Silt	NA	0
				7.0	.34	<.01	Silt	Gravel	5
				10.0	.32	<.01	Gravel	Silt	2
				Trans	sect 5 (Riffle)				
5.0	322	49	40	1.2	.09	.12	Cobble	Gravel	4
				2.5	1.13	.81	Cobble	Gravel	4
				3.9	.08	.37	Cobble	Gravel	4
				Trans	sect 6 (Riffle)				
10.8	347	55	75	3.4	.08	.03	Gravel	Cobble	5
				6.4	¹ .11	.40	Gravel	Cobble	5
				10.2	.08	.16	Gravel	Sand	5

¹Thalweg.




Figure 5. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach B, San Pedro River near Hereford Road, Arizona, based on measurements made December 18, 1996.




Figure 6. Bed-material at transects 1–6 and average for reach B, San Pedro River near Hereford Road, Arizona, December 18, 1996.

Table 6. Density and dominance of woody vegetation for reach B, San Pedro River near Hereford Road, Arizona, December 18, 1996 [Length of reach, 328 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Fremont cottonwood (Populus fremontii)	850	484	67	41
Willow (Salix sp.)	318	258	75	59

 Table 7.
 Habitat characteristics of reach C, San Pedro River near Hereford Road, Arizona, December 17, 1996

[Embeddedness categories: 0, no gravel, cobbles, or boulders present; 1, more than 75 percent covered by fine sediment; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment. NA, not applicable; <, less than]

		Can	ору		Velocity		Sub	strate	
	Aspect, in degrees	Angle, in degrees	Density,	Distance from left bank, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness
				7	Transect 1 (Riffle)				
2.6	245	84	34	1.0	0.09	0.91	Cobble	Gravel	4
				1.5	¹ .12	.38	Cobble	Gravel	4
				2.0	.10	.27	Cobble	Gravel	4
				7	Transect 2 (Riffle)				
3.2	206	114	25	.6	.05	.43	Cobble	NA	4
				1.4	¹ .11	.84	Cobble	NA	4
				2.0	.08	.32	Cobble	NA	4
					Transect 3 (Pool)				
4.1	305	75	94	1.7	1.52	.07	Cobble	Silt	3
				2.6	.49	.12	Cobble	Silt	3
				3.2	.21	.03	Cobble	Silt	1
					Transect 4 (Run)				
10.5	343	102	15	2.4	.30	<.01	Silt	Gravel	5
				4.9	¹ .36	.02	Silt	Gravel	5
				7.3	.30	.04	Silt	Gravel	5
					Transect 5 (Run)				
3.4	301	139	22	1.4	.12	.13	Gravel	Silt	5
				1.9	¹ .27	<.01	Silt	Gravel	5
				2.5	.18	.07	Silt	Cobble	0
				7	Transect 6 (Riffle)				
11.8	361	99	35	3.7	.07	.41	Cobble	Gravel	3
				4.7	¹ .10	.63	Gravel	Cobble	3
				11.0	.05	.13	Cobble	NA	3

¹Thalweg.




Figure 7. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach C, San Pedro River near Hereford Road, Arizona, based on measurements made December 19, 1996.




Figure 8. Bed-material types at transects 1–6 and average for reach C, San Pedro River near Hereford Road, Arizona, December 19,1996.

Density and dominance of woody vegetation for reach C, San Pedro River near Hereford Road, Arizona, December 17, 1996 [Length of reach, 365 meters. <, less than]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Fremont cottonwood (Populus fremontii)	363	214	100	76
Mesquite (Prosopis sp.)	13	<1	8	4
Willow (Salix sp.)	229	37	42	20

San Pedro River near Hig (USGS station number: 3	ghway 90, Arizona 313256110080701)	




Figure 9. Location of transects 1–6, reaches A–C, San Pedro River near Highway 90, Arizona.

Table 9. Habitat characteristics of reach A, San Pedro River near Highway 90, Arizona, December 5, 1996

[Embeddedness categories: 0, no gravel, cobbles, or boulders present; 2, 51 to 75 percent covered by fine sediment; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment. <, less than]

		Canopy			Velocity			Substrate		
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness	
				Tra	ansect 1 (Run)					
5.5	345	95	4	2.0	0.27	² <0.01	Sand	Silt	0	
				4.1	¹ .46	.22	Sand	Silt	0	
				4.8	.27	.09	Silt	Sand	0	
				Tra	nsect 2 (Riffle)					
2.2	306	82	12	.8	1.27	.21	Gravel	Sand	5	
				1.5	.21	.67	Gravel	Cobble	4	
				1.9	.08	.21	Silt	Sand	0	
				Tra	ansect 3 (Run)					
2.6	296	75	22	.8	.27	.17	Sand	Cobble	3	
				1.5	1.40	.63	Cobble	Sand	3	
				2.0	.32	² .02	Sand	Silt	2	
				Tra	nsect 4 (Riffle)					
3.6	277	47	18	.9	.12	.27	Cobble	Gravel	3	
				1.6	1.18	.54	Cobble	Gravel	3	
				2.3	.12	.43	Cobble	Gravel	3	
				Tra	ansect 5 (Pool)					
4.1	327	47	63	.2	.67	.12	Cobble	Gravel	3	
				1.1	1.73	.10	Cobble	Gravel	2	
				1.8	.73	.05	Cobble	Gravel	2	
				Tra	ansect 6 (Run)					
2.5	333	69	7	.7	.12	.50	Gravel	Cobble	3	
				1.2	.21	.56	Gravel	Cobble	3	
				1.8	1.23	.24	Sand	Gravel	5	

¹Thalweg. ²Reverse flow.




Figure 10. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, San Pedro River near Highway 90, Arizona, based on measurements made December 5, 1996.




Figure 11. Bed-material types at transects 1–6 and average for reach A, San Pedro River near Highway 90, Arizona, December 5, 1996.

Table 10. Density and dominance of woody vegetation for reach A, San Pedro River near Highway 90, Arizona, December 5, 1996 [Length of reach, 274 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Fremont cottonwood (Populus fremontii)	383	406	50	38
Willow (Salix sp.)	115	200	83	62

Table 11. Habitat characteristics of reach B, San Pedro River near Highway 90, Arizona, December 5, 1996

[Embeddedness categories: 0, no gravel, cobbles, or boulders present; 1, more than 75 percent covered by fine sediment; 2, 51 to 75 percent covered by fine sediment; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment. <, less than]

		Can	юру		Velocity		Sub	strate		
Stream width, in meters	Aspect, in degrees	Angle, in degrees	Density, in percent	Distance from left bank, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness	
				Tra	nsect 1 (Riffle)					
3.6	313	35	48	0.8	0.20	0.53	Gravel	Sand	5	
				1.6	1.29	.36	Sand	Gravel	5	
				2.6	.22	<.01	Silt	Sand	0	
				Tra	ansect 2 (Pool)					
8.3	342	76	65	2.5	.21	<.01	Sand	Silt	0	
				5.0	.31	.08	Sand	Silt	0	
				7.4	1.46	.13	Sand	Silt	0	
				7.8	.41	.07	Sand	Silt	0	
				Tra	nsect 3 (Riffle)					
4.6	268	88	9	1.3	.08	.24	Cobble	Gravel	3	
				2.6	1.13	.94	Cobble	Gravel	4	
				3.6	.08	.22	Cobble	Gravel	3	
				Tr	ansect 4 (Pool)					
4.9	302	39	78	1.9	.38	.04	Cobble	Silt	1	
				3.8	1.52	.16	Cobble	Sand	2	
				4.4	.52	.11	Cobble	Sand	2	
				Tra	nsect 5 (Riffle)					
3.8	321	59	35	1.9	.15	.92	Cobble	Gravel	3	
				2.0	1.18	.19	Cobble	Gravel	4	
				2.9	.09	.26	Cobble	Gravel	4	
				Tra	ansect 6 (Pool)					
5.5	317	124	70	1.3	.20	.14	Cobble	Sand	1	
				2.6	.25	.13	Cobble	Sand	3	
				3.8	1.40	.10	Silt	Cobble	1	

¹Thalweg.




Figure 12. Monthly distribution of solar insolation at transects 1, 5, 6, and midreach, reach B, San Pedro River near Highway 90, Arizona, based on measurements made December 5, 1996.




Figure 13. Bed-material types at transects 1–6 and average for reach B, San Pedro River near Highway 90, Arizona, December 5, 1996.

Table 12. Density and dominance of woody vegetation for reach B, San Pedro River at Highway 90, Arizona, December 5, 1996 [Length of reach, 197 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Fremont cottonwood (Populus fremontii)	989	623	58	20
Mesquite (Prosopis sp.)	7	1	8	3
Willow (Salix sp.)	98	236	100	77

Table 13. Habitat characteristics of reach C, San Pedro River near Highway 90, Arizona, December 6, 1996

[Embeddedness categories: 0, no gravel, cobbles, or boulders present; 3, 26 to 50 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment. <, less than]

		Canopy			Velocity		Sub	strate		
Stream width, n meters	Aspect, in degrees	Angle, in degrees	Density,	Distance from left bank, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	- Embeddedness	
				Т	ransect 1 (Riffle)					
1.9	343	59	26	0.6	0.19	0.07	Silt	Sand	0	
				1.2	1.40	.52	Gravel	Sand	5	
				1.4	.27	.27	Sand	Gravel	5	
				ŗ	Transect 2 (Pool)					
10.6	1	44	25	1.4	.41	.01	Silt	Sand	0	
				2.8	.30	.03	Sand	Silt	0	
				5.6	.22	.06	Silt	Sand	0	
				8.4	¹ .54	.04	Silt	Sand	0	
				Т	ransect 3 (Riffle)					
10.8	357	40	35	.6	1.20	.45	Cobble	Gravel	5	
				1.8	.07	.34	Cobble	Gravel	3	
				8.8	.20	.01	Sand	Gravel	5	
				9.8	.18	0	Sand	Silt	0	
				ŗ	Transect 4 (Pool)					
6.4	355	46	53	1.6	.70	.05	Sand	Gravel	5	
				3.2	.72	.06	Sand	Gravel	5	
				4.8	¹ .73	.03	Sand	Gravel	5	
				ŗ	Transect 5 (Pool)					
10.2	355	46	40	2.1	¹ .67	.04	Silt	Sand	0	
				4.8	.36	.36	Sand	Silt	0	
				7.5	.21	.21	Sand	Silt	0	
				ŗ	Transect 6 (Pool)					
8.3	19	33	43	2.5	1.84	² <.01	Sand	Silt	0	
				5.0	.75	.12	Sand	Silt	0	
				6.6	.67	.02	Sand	Silt	0	

¹Thalweg. ²Reverse flow.




Figure 14. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach C, San Pedro River near Highway 90, Arizona, based on measurements made December 6, 1996.

200





Figure 15. Bed-material types at transects 1–6 and average for reach C, San Pedro River near Highway 90, Arizona, December 6, 1996.

 Table 14.
 Density and dominance of woody vegetation for reach C, San Pedro River near Highway 90, Arizona, December 6, 1996
 [Length of reach, 310 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Fremont cottonwood (Populus fremontii)	574	1,022	42	24
Willow (Salix sp.)	86	484	83	76






Figure 16. Location of transects 1–6, reaches A–C, San Pedro River at Charleston, Arizona.





Figure 17. Longitudinal profile, reach A, San Pedro River at Charleston, Arizona, January 28 and 29, 1998. Local datum established using arbitrary elevation.

 Table 15.
 Cross-sectional survey data for reach A, San Pedro River at Charleston, Arizona, January 28 and 29, 1998
 [All values are in meters. Distance is from left end point]

Trans	ect A1	Trans	ect A2	Trans	ect A3	Trans	ect A4	Trans	ect A5	Trans	ect A6
Distance	Elevation										
-7.3	14.1	0.0	14.5	3.0	16.2	5.5	15.5	0.0	16.2	0.0	15.8
0.0	14.1	5.8	14.5	5.5	15.1	7.6	15.2	3.0	15.2	3.4	15.2
0.0	12.2	7.3	12.6	8.5	14.8	8.5	14.4	6.1	14.5	4.6	14.8
4.3	10.4	11.3	11.3	11.6	14.3	9.8	14.0	8.5	13.9	5.8	14.4
6.7	10.1	11.9	10.2	13.1	13.9	12.2	13.7	11.6	13.3	6.7	14.1
8.2	9.5	14.0	10.6	14.3	13.4	14.0	13.3	15.2	12.8	7.9	13.7
8.7	9.5	18.9	10.7	15.8	13.0	17.1	12.7	19.5	12.6	8.5	13.7
9.4	9.2	21.3	10.6	17.7	12.3	21.0	12.5	25.0	12.4	10.1	13.2
10.1	8.5	21.9	10.6	19.2	11.8	21.9	12.3	25.3	12.5	11.0	12.8
11.6	8.8	22.3	11.4	19.5	11.3	22.4	11.9	27.4	12.5	12.8	12.7
14.0	8.4	25.6	11.5	20.1	11.3	23.2	11.6	30.2	12.4	14.6	12.8
14.6	8.6	26.8	12.1	21.3	11.5	24.4	11.6	30.5	12.1	15.8	12.7
14.9	9.1	29.0	12.0	22.9	11.6	25.6	11.6	30.8	11.9	17.1	12.6
15.7	9.5	29.9	11.2	24.1	11.6	26.4	11.8	31.7	12.0	19.2	12.6
20.7	9.5	31.1	10.9	25.0	12.3	27.7	12.3	33.2	12.1	20.7	12.6
21.3	9.9	34.7	11.5	27.4	12.5	29.6	12.3	35.1	12.2	22.6	12.7
23.2	10.6	35.1	11.9	28.7	12.2	31.4	12.6	36.3	12.3	24.1	12.7
25.0	10.3	37.8	12.1	33.5	12.4	32.3	12.2	37.2	12.2	25.9	12.6
27.4	10.3	41.5	12.5	38.4	12.4	33.8	12.3	38.1	11.9	27.1	12.8
28.3	10.6	47.5	12.6	40.2	12.5	35.7	12.2	39.0	12.1	27.7	13.0
36.0	11.1	48.5	12.8	41.8	12.9	37.2	12.6	39.6	12.8	29.9	13.2
39.3	10.8	51.2	12.9	43.0	12.9	38.1	12.4	40.5	13.3	32.9	12.9
40.5	10.9	58.5	13.5	44.8	13.4	39.9	12.3	41.5	13.9	34.7	13.0
43.3	10.3	76.5	15.5	46.3	13.4	42.1	12.3	42.2	14.5	36.0	13.1
46.9	10.3			48.2	13.6	43.9	13.5			37.8	13.2
51.8	10.8			50.6	13.9	45.7	13.7			39.6	13.7
56.1	11.1			54.9	14.3	47.5	14.2			40.8	14.1
65.8	11.7			57.0	15.1	50.0	14.4			42.1	14.9
70.9	13.1					51.8	14.6				







Figure 18A-F. Cross sections of channel reach, reach A, San Pedro River at Charleston, Arizona, January 28 and 29, 1998. A, Transect A1. B, Transect A2. C, Transect A3. D, Transect A4. E, Transect A5. F, Transect A6. Local datum established using arbitrary elevation.







Figure 18A-F. Continued






Figure 18A-F. Continued.

Table 16. Description and location of semipermanent monuments for reach A, San Pedro River at Charleston, Arizona, January 28 and 29, 1998

Transect	Туре	Description of location and reference marks
A1	Left	Rebar. Transect is under cableway. Reference mark, RM-1, is spike in downstream side of large cottonwood tree, at tributary mouth upstream from transect 2. Elevation 15.24 meters.
A1	Right	Rebar, transect is under cableway.
A2	Left	Rebar, 56 meters upstream from transect A1.
A2	Right	Rebar, 56 meters upstream from transect A1.
A3	Left	Rebar, 70 meters upstream from transect A2.
A3	Right	Rebar, 70 meters upstream from transect A2.
A4	Left	Rebar, 88 meters upstream from transect A3.
A4	Right	Rebar, 88 meters upstream from transect A3.
A5	Left	Rebar, 75 meters upstream from transect A4.
A5	Right	Rebar, 75 meters upstream from transect A4.
A6	Left	Rebar, 99 meters upstream from transect A5.
A6	Right	Rebar, 99 meters upstream from transect A5.

Table 17. Habitat characteristics of reach A, San Pedro River at Charleston, Arizona, December 8, 1995

[Embeddedness categories: 0, no gravel, cobbles, or boulders present; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment. NA, not applicable]

		Can	юру		Velocity		Substrate			
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness	
				Tr	ransect 1 (Run)					
3.5	355	76	44	0.5	10.50	0.24	Sand	Gravel	5	
				1.5	.28	.34	Sand	NA	0	
				2.5	.15	.08	Sand	NA	0	
				Tra	ansect 2 (Riffle)					
13.6	307	78	42	.8	.07	.20	Gravel	Sand	5	
				10.9	¹ .12	.48	Sand	Gravel	5	
				12.7	.11	.43	Sand	Gravel	5	
				Tr	ransect 3 (Run)					
7.0	296	67	25	.8	1.43	.31	Gravel	NA	5	
				2.5	.23	.21	Silt	Sand	0	
				4.0	.21	.05	Silt	Sand	0	
				Tr	ransect 4 (Run)					
2.5	276	76	4	.8	1.23	.62	Gravel	Cobble	4	
				1.4	.18	.53	Gravel	Cobble	4	
				Tra	ansect 5 (Riffle)					
6.9	348	67	19	1.2	.08	.11	Gravel	Cobble	3	
				3.1	.10	.22	Gravel	Sand	3	
				6.2	¹ .14	.53	Sand	Gravel	3	
				Tra	ansect 6 (Riffle)					
14.5	318	68	24	1.0	1.20	.57	Gravel	Cobble	4	
				1.9	.14	.53	Gravel	NA	4	
				11.5	.06	.22	Gravel	Sand	4	

¹Thalweg.




Figure 19. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, San Pedro River at Charleston, Arizona, based on measurements made December 8, 1995.




Figure 20. Bed-material types at transects 1–6 and average for reach A, San Pedro River at Charleston, Arizona, December 8, 1995.

 Table 18.
 Density and dominance of woody vegetation for reach A, San Pedro River at Charleston, Arizona, December 8,1995
 [Length of reach, 388 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Fremont cottonwood (Populus fremontii)	2,285	845	50	31
Mesquite (Prosopis sp.)	50	2	8	4
Willow (Salix sp.)	426	328	83	65

 Table 19.
 Habitat characteristics of reach A, San Pedro River at Charleston, Arizona, November 13, 1996

[Embeddedness categories: 0, no gravel, cobbles, or boulders present; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment. Dashes indicate no data]

		Canopy			Velocity		Sub	strate	
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness
				Tran	sect 1 (Run)				
9.2	343	105	28	0.4	10.46	0.33	Gravel	Sand	5
				1.5	.27	.30	Gravel	Sand	5
				8.0	.20	0	Sand	Silt	0
				Trans	sect 2 (Riffle)				
13.1	300	77	65	1.4	.15	.76	Gravel	Sand	5
				8.8	1.21	.46	Sand	Gravel	5
				12.4	.09	.10	Sand	Gravel	5
				Tran	sect 3 (Run)				
7.0	295	71	15	.7	¹ .55	.22	Sand	Gravel	
				4.0	.27	.20	Sand	Gravel	
				6.0	.18	.17	Sand	Gravel	
				Tran	sect 4 (Run)				
3.3	276	76	3	.5	1.27	.37	Gravel	Sand	3
				1.5	.21	.46	Gravel	Sand	3
				2.5	.15	.23	Gravel	Sand	3
				Trans	sect 5 (Riffle)				
8.1	276	63	34	1.3	1.24	.43	Cobble	Gravel	4
				2.5	.12	.37	Cobble	Gravel	4
				7.5	.12	.54	Cobble	Gravel	4
				Trans	sect 6 (Riffle)				
11.9	312	75	15	1.0	.06	.16	Gravel	Sand	5
				8.4	.18	.51	Gravel	Sand	4
				9.4	1.24	.24	Gravel	Sand	4

¹Thalweg.




Figure 21. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, San Pedro River at Charleston, Arizona, based on measurements made December 8, 1995.




Figure 22. Bed-material types at transects 1–6 and average for reach A, San Pedro River at Charleston, Arizona, December 8, 1995.

Table 20. Density and dominance of woody vegetation for reach A, San Pedro River at Charleston, Arizona, November 13, 1996 [Length of reach, 394 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Fremont cottonwood (Populus fremontii)	242	58	25	16
Mesquite (Prosopis sp.)	66	19	33	20
Willow (Salix sp.)	419	394	92	64

Table 21. Habitat characteristics of reach B, San Pedro River at Charleston, Arizona, November 18, 1996

[Embeddedness categories: 0, no gravel, cobbles, or boulders present; 2, 51 to 75 percent covered by fine sediment; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment. NA, not applicable]

		Canopy			Velocity		Sub	strate		
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness	
				Trans	sect 1 (Riffle)					
12.8	336	137	35	1.4	0.06	0.02	Silt	Gravel	5	
				9.0	.12	.25	Gravel	Sand	5	
				10.7	.30	.30	Gravel	Sand	5	
				12.2	1.43	.16	Sand	Gravel	5	
				Tran	sect 2 (Pool)					
8.5	349	46	43	1.5	.36	.07	Gravel	NA	5	
				3.2	1.43	.13	Gravel	Silt	5	
				5.5	.30	.13	Sand	NA	0	
				Tran	sect 3 (Pool)					
8.7	332	50	35	1.7	1.43	.12	Gravel	Silt	5	
				3.5	.40	.16	Sand	Gravel	5	
				5.2	.21	.08	Sand	Gravel	5	
				Trans	sect 4 (Riffle)					
11.0	327	100	25	.5	1.43	.59	Gravel	NA	5	
				1.6	.37	.04	Gravel	NA	5	
				2.0	.21	.30	Gravel	Sand	5	
				7.1	.03	.30	Gravel	Cobble	4	
				Tran	sect 5 (Pool)					
5.3	301	72	66	1.8	.30	.03	Gravel	NA	5	
				3.5	1.36	.35	Cobble	Gravel	2	
				4.4	.30	.29	Gravel	NA	5	
				Trans	sect 6 (Riffle)					
10.6	333	114	40	3.5	.12	.34	Cobble	Gravel	3	
				5.5	1.21	.65	Cobble	Gravel	3	
				7.4	.19	.19	Cobble	Sand	3	
Thalwag										

¹Thalweg.




Figure 23. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach B, San Pedro River at Charleston, Arizona, based on measurements made November 18, 1996.

900




Figure 24. Bed-material at transects 1–6 and average for reach B, San Pedro River at Charleston, Arizona, November 18, 1996.

Table 22. Density and dominance of woody vegetation for reach B, San Pedro River at Charleston, Arizona, November 18, 1996 [Length of reach, 208 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Fremont cottonwood (Populus fremontii)	1,420	2,059	42	24
Mesquite (Prosopis sp.)	83	131	50	26
Willow (Salix sp.)	136	412	58	50

Table 23. Habitat characteristics of reach C, San Pedro River at Charleston, Arizona, November 22, 1996

[Embeddedness categories: 0, no gravel, cobbles, or boulders present; 2, 51 to 75 percent covered by fine sediment; 3, 26 to 50 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment]

		Can	юру		Velocity		Sul		
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness
				Tran	sect 1 (Riffle)				
4.2	318	106	7	1.1	10.8	0.86	Cobble	Gravel	3
				1.7	.15	.85	Cobble	Gravel	3
				2.8	.12	.47	Cobble	Gravel	3
				Tra	nsect 2 (Pool)				
8.0	318	98	29	1.0	1.43	.04	Sand	Gravel	5
				3.0	.26	.04	Sand	Gravel	5
				5.0	.24	.14	Sand	Gravel	5
				Tra	nsect 3 (Pool)				
5.8	337	75	44	2.0	.12	.31	Gravel	Cobble	3
				3.5	.15	.39	Gravel	Cobble	3
				5.0	1.27	.51	Gravel	Cobble	3
				Transe	ect 4 (Run/Poo	ol)			
6.4	4	80	48	1.9	.49	.11	Gravel	Cobble	2
				3.3	¹ .64	.16	Cobble	Gravel	2
				4.0	.61	.15	Cobble	Gravel	5
				Tra	nsect 5 (Run)				
3.1	43	98	40	1.3	.21	.52	Gravel	Cobble	3
				2.0	.27	.58	Gravel	Cobble	3
				2.6	1.30	.48	Gravel	Cobble	3
				Tran	sect 6 (Riffle)				
3.1	53	88	13	1.2	1.24	.96	Gravel	Cobble	2
				1.7	.18	.82	Gravel	Cobble	2
				2.4	.12	.54	Gravel	Cobble	2

¹Thalweg.




Figure 25. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach C, San Pedro River at Charleston, Arizona, based on measurements made November 22, 1996.




Figure 26. Bed-material at transects 1–6 and average for reach C, San Pedro River at Charleston, Arizona, November 22, 1996.

Table 24. Density and dominance of woody vegetation for reach C, San Pedro River at Charleston, Arizona, November 22, 1996 [Length of reach, 311 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Fremont cottonwood (Populus fremontii)	2,215	886	33	22
Mesquite (Prosopis sp.)	20	31	7	9
Willow (Salix sp.)	55	70	75	70

Table 25. Habitat characteristics of reach A, San Pedro River at Charleston, Arizona, November 20, 1997

[Embeddedness categories: 0, no gravel, cobbles, or boulders present; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment. NA, not applicable]

		Can	юру	oy Velocity			Substrate		
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness
				Transe	ct 1 (Riffle)				
5.2	1	96	7	1.9	10.88	0.08	Gravel	Sand	5
				2.6	.82	.06	Gravel	Muck	5
				3.7	.73	.06	Gravel	Muck	5
				Transc	ect 2 (Pool)				
9.1	293	88	28	.2	¹ .55	.01	Sand	NA	0
				5.4	.09	.34	Gravel	NA	5
				7.3	.21	.50	Gravel	NA	5
				Transe	ect 3 (Pool)				
5.0	295	73	32	.3	1.40	.47	Gravel	NA	5
				2.0	.09	.25	Gravel	NA	5
				4.0	.06	.31	Gravel	NA	5
				Transect	4 (Run/Pool)				
3.1	276	72	16	.5	.20	.24	Gravel	Sand	5
				1.0	1.26	.46	Gravel	Cobble	5
				2.1	.23	.32	Gravel	Cobble	5
				Transe	ect 5 (Run)				
17.5	348	110	13	2.1	.06	.02	Gravel	Cobble	3
				11.0	1.21	.93	Cobble	Gravel	4
				11.9	.09	.56	Gravel	Cobble	3
				Transe	ct 6 (Riffle)				
16.1	273	79	50	3.5	.12	.14	Cobble	Gravel	4
				7.4	1.29	.11	Gravel	Cobble	3
				11.5	.09	.01	Gravel	Sand	4

¹Thalweg.




Figure 27. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, San Pedro River at Charleston, Arizona, based on measurements made November 2, 1997.




Figure 28. Bed-material types at transects 1–6 and average for reach A, San Pedro River at Charleston, Arizona, November 20, 1997.

Table 26. Density and dominance of woody vegetation for reach A, San Pedro River at Charleston, Arizona, November 20, 1997 [Length of reach, 401 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Fremont cottonwood (Populus fremontii)	1,462	556	58	28
Mesquite (Prosopis sp.)	60	16	33	19
Willow (Salix sp.)	358	261	92	53






Figure 29. Location of transects 1–6, reach A, Gila River at Kelvin, Arizona.





Figure 30. Longitudinal profile, reach A, Gila River at Kelvin, Arizona, November 3 and 4, 1998. Local datum is the zero point of the reference gage at streamflow-gaging station, Gila River at Kelvin (09474000).

Table 27. Cross-sectional survey data for reach A, Gila River at Kelvin, Arizona, November 3 and 4, 1998 [All values are in meters. Distance is from left end point]

Transect A1		Transect A2		Transect A3		Transect A4		Transect A5		Transect A6	
Distance	Elevation										
0.0	32.9	0.0	32.0	0.0	32.2	0.0	32.2	0.0	31.6	0.0	31.6
3.8	32.5	4.9	31.6	6.7	31.4	2.8	32.2	0.9	31.2	1.2	31.3
6.1	32.1	9.8	31.9	10.7	32.1	7.8	32.1	2.4	31.3	2.4	31.2
9.4	31.6	10.5	32.1	12.8	30.8	12.2	31.8	4.1	31.3	4.3	31.5
12.7	30.9	14.0	31.1	13.5	30.2	13.6	31.8	8.7	31.2	5.5	31.7
13.3	30.7	15.9	30.8	14.7	29.7	14.2	31.6	13.1	31.0	8.5	31.8
18.8	30.2	16.8	30.4	18.8	29.8	15.9	31.4	14.6	30.8	9.8	31.8
22.0	29.8	20.0	30.2	22.0	29.9	17.3	31.4	16.2	30.5	10.7	31.5
28.1	30.2	27.0	29.9	28.6	29.8	19.2	31.0	16.7	30.7	11.3	31.4
35.8	30.3	33.4	30.1	31.1	30.2	20.7	30.9	17.3	30.6	12.2	31.3
39.0	30.1	36.5	30.1	32.7	30.8	21.5	30.6	18.1	30.3	14.9	31.2
41.2	30.0	40.4	30.2	34.8	31.2	24.1	30.3	19.0	29.9	16.8	31.3
43.3	29.8	42.8	31.4	38.5	32.7	25.5	30.1	19.7	29.8	18.3	31.1
44.3	29.7	45.3	32.7	40.0	33.4	26.7	29.7	20.8	29.6	20.1	31.0
44.7	30.9	47.9	33.5			28.7	29.6	22.6	29.7	21.3	31.2
46.8	32.0					30.9	29.5	24.5	29.5	23.2	31.1
50.5	33.1					32.7	29.4	25.3	29.6	25.0	30.8
						33.7	29.4	26.6	30.0	27.4	30.8
						35.1	29.7	27.0	30.0	29.0	30.7
						36.5	30.2	27.6	30.3	29.9	30.7
						37.0	30.5	28.2	31.7	30.8	30.8
						37.8	31.2			32.0	30.9
						39.2	32.3			33.2	31.1
						40.5	33.3			34.1	31.7
										34.7	32.0
										35.1	32.6
										35.4	32.8







Figure 31 A-F. Cross sections of channel, reach A, Gila River at Kelvin, Arizona, November 3 and 4, 1998. A, Transect A1. B, Transect A2. C, Transect A3. D, Transect A4. E, Transect A5. F, Transect A6. Local datum is the zero point of the reference gage at streamflow-gaging station, Gila River at Kelvin, Arizona (09474000).







Figure 31 A-F. Continued.






Figure 31 A-F. Continued.

Table 28. Description and location of semipermanent monuments for reach A, Gila River at Kelvin, Arizona, November 3 and 4, 1998

Transect	Туре	Description of location and reference marks
A1	Left	Rebar. Reference mark, RM-6, is well; brass tablet at gaging station, 1.5 meters downstream from upper gaging station. Elevation, 32.63 meters, datum of survey.
A1	Right	No marker.
A2	Left	Rebar, 50 meters upstream from transect A1.
A2	Right	Rebar, 50 meters upstream from transect A1.
A3	Left	Rebar, 55 meters upstream from transect A2.
A3	Right	Rebar, 55 meters upstream from transect A2.
A4	Left	Rebar, 77 meters upstream from transect A3.
A4	Right	Rebar, 77 meters upstream from transect A3.
A5	Left	Rebar, 82 meters upstream from transect A4.
A5	Right	Rebar, 82 meters upstream from transect A4.
A6	Left	Rebar, 107 meters upstream from transect A5.
A6	Right	Rebar, 107 meters upstream from transect A5.

Table 29. Habitat characteristics of reach A, Gila River at Kelvin, Arizona, November 27, 1995

[Embeddedness categories: 0, no gravel, cobbles, or boulders present; 2, 51 to 75 percent covered by fine sediment; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment. Dashes indicate no data. NA, not applicable]

		Car	юру		Velocity		Sub	strate		
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness	
				Tra	nsect 1 (Riffle))				
26.5	319	132	43	5.0	0.24	0.60	Cobble	Gravel	4	
				15.1	.18	.60	Cobble	Gravel	4	
				22.0	1.72	.94	Cobble	Boulder	4	
				Tra	ansect 2 (Run)					
28.7	329	140	26	9.0	.29	.29	Gravel	Sand	2	
				17.0	.34	.49	Cobble	Sand	2	
				25.3	1.63	.70	Gravel	Cobble	3	
				Tra	ansect 3 (Pool)					
24.5	319	121	32	3.9	¹ .71	.36	Sand	Cobble	3	
				9.0	.43	.38	Sand	NA	0	
				17.0	.40	.35	Sand	NA	0	
				Tra	ansect 4 (Run)					
16.1	315	112	25	4.0	.62	.25	Sand	Cobble	2	
				8.0	.75	.45	Sand	NA	0	
				12.6	¹ 1.09	.46	Sand	NA	0	
				Tra	ansect 5 (Run)					
15.6	344	98	26	3.3	.30	.32				
				6.7	.45	.35	Sand	Gravel	4	
				10.0	1.86	.86	Gravel	Sand	4	
				Tra	nsect 6 (Riffle))				
32.5	281	141	19	2.0	1.46	.44	Gravel	Cobble	4	
				12.5	.25	.18	Cobble	Sand	4	
				22.5	.18	.66	Cobble	Gravel	4	

¹Thalweg.




Figure 32. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, Gila River at Kelvin, Arizona, based on measurements made November 27, 1995.




Figure 33. Bed-material types at transects 1–6 and average for reach A, Gila River at Kelvin, Arizona, November 27, 1995.

Table 30. Density and dominance of woody vegetation for reach A, Gila River at Kelvin, Arizona, November 27, 1995
 [Length of reach, 371 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Mesquite (Prosopis sp.)	50	50	8	3
Tamarisk (Tamarix sp.)	25	61	92	71
Willow (Salix sp.)	346	308	42	26






Figure 34. Location of transects 1–6, reach A, Santa Cruz River at Tubac, Arizona.





Figure 35. Longitudinal profile, reach A, Santa Cruz River at Tubac, Arizona, January 7 and 12, 1998. Local datum established by using arbitrary elevation.

Table 31. Cross-sectional survey data for reach A, Santa Cruz River at Tubac, Arizona, January 7 and 12, 1998 [All values are in meters. Distance is from left end point]

Trans	ect A1	Trans	ect A2	Trans	ect A3	Trans	ect A4	Trans	ect A5	Trans	ect A6
Distance	Elevation										
0	31.7	0	29.6	0	30.7	0	30.9	0	31.6	0	31.4
4.9	29.6	1	29.3	4.9	29.6	4.8	29.3	0	31.4	0	31.3
9.8	29.8	9.6	29.4	21.2	29.8	13.6	29.3	1.4	31.2	.3	31.2
14.0	29.4	12.4	29.2	32.5	29.9	22.5	29.4	3.9	30.7	1.5	30.7
18	29.7	17	29.4	63.3	31	35.3	29.8	16.5	31	8.4	30.7
22.6	29.9	18.6	29.7	76.2	30.6	37.9	30.4	18.9	30.2	8.9	29.6
23.2	29.6	22.7	29.4	86.3	30.5	46.3	30.2	27	30.2	10.1	29.4
29	29.4	27.7	29.3	89.7	30.6	57.2	30	39.6	29.4	15.6	29.8
31.4	29.3	31	30	94.2	29.9	59.6	30.7	42.2	30.1	19.5	30.3
34.2	29.3	36.8	30	101.6	29.8	69.3	30.8	45.6	30.1	23.8	30.4
40.3	29.5	46.8	30	106.8	29.6	78.2	31.1	50	30.8	28	30.6
43.6	29.4	55.6	30	110.6	28.6	86.9	30.9	55	30.9	30.8	30.8
47.9	30	60.8	30.3	111.1	28.3	103.5	30.7	62.3	31.1	33.8	31
52.2	30	73.3	30.1	113.4	28.3	108.5	29.2	74.3	30.9	35.1	30.7
61.3	30.1	82	29.9	116.6	28.4	110.4	28.9	81.3	30.7	36.3	30.6
68	30	88.3	30.1	117	28.8	116.6	29.2	92.6	30.9	38.8	30.8
73.2	30.2	95.7	29.5	120.8	28.8	120.2	29.0	95.3	31.1	40.6	30.6
80.8	29.9	98.9	29.5	123.3	28.8	120.9	28.4	103.8	29.5	42.7	30.6
89	30.2	100.7	29.1	125.9	28.9	122.8	28.4	104.7	28.9	46.1	30.7
93.6	29.0	103.6	29.3	130.4	29.4	125.3	28.4	105	28.6	47.3	30.9
95.1	29.5	105.8	28.4	133.8	29.3	125.9	29.0	107.6	28.7	55.5	30.8
100	29.5	109.3	28.7	137.6	29.1	129.7	29.2	110.9	28.8	60.2	30.9
107.3	29.0	113.3	29.0	142.9	28.6	131.8	29.4	111.8	29.3	64.5	30.7
107.6	28.6	114.2	28.6	145.6	29.4	136.6	29.4	116.9	29.3	69.4	30.7
110.1	28.5	116.7	28.6			140.5	29.5	125	29.3	76.4	30.8
112.5	28.5	117.6	28.7			143.4	29.3	131.6	29.3	77.9	30.2
114	29.1	119.6	28.2			145.7	29.1	135.5	30.2	82.7	30.1
118	29	119.6	28.1			147.6	29.1	138.9	30.4	86.8	29.9
122.3	29.1	121.7	28.1			148.8	29.8	147.2	34	90.9	29.2
127.7	28.8	124	28.3			151.3	31.1	156	34.4	95.5	28.8
130.2	28.4	124.6	28.7			155.1	30.8			95.8	28.8
132.9	28.3	129.4	28.6			160.2	34.1			97.7	28.8
132.9	28.1	136	28.7			161.8	34.3			98.9	28.8
133.2	28	140.6	29.2							101.8	29
135.1	28	144.7	28.6							104.5	29
138.4	28	146	28.5							105.1	29.4
138.7	28.0	151.8	28.9							110.1	29.5
139.9	28.4	154.5	29.3							119.6	30.1
143	28.3	158.8	29.1							120.1	31
146	28.8	163.3	31.1								
146.3	29.1										
150	31.8										







Figure 36A-F. Cross sections of channel, reach A, Santa Cruz River at Tubac, Arizona, January 7 and 12, 1998. A, Transect A1. B, Transect A2. C, Transect A3. D, Transect A4. E, Transect A5. F, Transect A6. Local datum established using arbitrary elevation.

C. Transect A3







Figure 36A-F. Continued.






Figure 36A-F. Continued.

Table 32. Description and location of semipermanent monuments for reach A, Santa Cruz River at Tubac, Arizona, January 12, 1998

Transect	Туре	Description of location and reference marks
RM-1		Red paint on levee about 20 meters downstream from transect A1. Elevation is 31.7 meters.
A1	Left	Red paint on levee.
A1	Right	No marker.
A2	Left	Red paint on levee 38 meters upstream from transect A1.
A2	Right	38 meters upstream from transect A1. No marker.
A3	Left	Red paint on levee 71 meters upstream from transect A2.
A3	Right	71 meters upstream from transect A2. No marker.
A4	Left	Red paint on levee 75 meters upstream from transect A3.
A4	Right	75 meters upstream from transect A3. No marker.
A5	Left	68 meters upstream from transect A4. No marker.
A5	Right	68 meters upstream from transect A4. No marker.
A6	Left	110 meters upstream from transect A5. No marker.
A6	Right	110 meters upstream from transect A5. No marker.

Table 33. Habitat characteristics of reach A, Santa Cruz River at Tubac, Arizona, January 19, 1996

[Embeddedness categories: 0, no gravel, cobbles, or boulders present; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment. NA, not applicable]

		Can	юру		Velocity		Sub	strate		
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness	
				Tra	nsect 1 (Run)					
6.7	10	128	9	1.7	0.26	0.48	Sand	NA	0	
				2.8	1.27	.64	Sand	Gravel	5	
				4.2	.21	.55	Sand	NA	0	
				Tran	sect 2 (Riffle)					
8.4	18	149	0	2.9	.18	.07	Sand	Gravel	4	
				5.0	1.24	1.05	Sand	Cobble	3	
				6.3	.18	.75	Sand	Cobble	3	
				Tra	nsect 3 (Run)					
14.6	352	118	12	3.4	.21	.63	Sand	NA	0	
				6.5	.08	.06	Sand	NA	0	
				10.6	¹ .27	.71	Sand	NA	0	
				Tra	nsect 4 (Run)					
7.5	4	85	38	.9	1.24	.63	Sand	NA	0	
				3.0	.18	.66	Sand	NA	0	
				5.0	.12	.51	Sand	NA	0	
				Tra	nsect 5 (Run)					
15.2	350	144	31	3.8	1.24	.50	Sand	NA	0	
				5.7	.15	.57	Sand	NA	0	
				7.8	.18	.57	Sand	NA	0	
				Tran	sect 6 (Riffle)					
17.5	26	153	0	1.6	.24	.88	Gravel	Cobble	4	
				2.0	1.27	.82	Gravel	Cobble	4	
				2.8	.27	.76	Gravel	Cobble	4	
				6.6	.12	.08	Silt	NA	0	

¹Thalweg.




Figure 37. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, Santa Cruz River at Tubac, Arizona, based on measurements made January 19, 1996.




Figure 38. Bed-material types at transects 1–6 and average for reach A, Santa Cruz River at Tubac, Arizona, January 19, 1996.

Table 34. Density and dominance of woody vegetation for reach A, Santa Cruz River at Tubac, Arizona, January 19, 1996 [Length of reach, 371 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Willow (Salix sp.)	35	64	100	79
Freemont cottonwood (Populus fremontii)	18	8	42	18
Desert broom (Baccharis sarothroides)	38	3	8	4






Figure 39. Location of transects 1–6, reach A, Santa Cruz River at Cortaro, Arizona.





Figure 40. Longitudinal profile, reach A, Santa Cruz River at Cortaro, Arizona, January 26, 1998. Local elevation is the zero point of the reference gage at streamflow-gaging station, Santa Cruz River at Cortaro, Arizona (09486500).

Table 35. Cross-sectional survey data for reach A, Santa Cruz River at Cortaro, Arizona, January 26, 1998 [All values are in meters. Distance is from left end point]

Trans	ect A1	Trans	ect A2	Trans	ect A3	Trans	ect A4	Trans	ect A5	Trans	ect A6
Distance	Elevation										
-3.0	29.7	-1.8	30.3	-1.8	30.4	-1.8	30.4	0.0	29.4	2.1	31.7
-0.9	27.6	0.0	28.5	0.0	28.6	0.0	28.6	7.0	29.0	4.0	29.6
0.6	25.8	1.8	26.4	2.7	25.7	2.4	28.4	16.8	28.6	6.7	29.6
2.4	25.8	5.5	25.6	5.8	25.8	2.7	27.4	18.3	26.3	7.9	28.6
7.6	26.1	8.8	25.8	8.8	26.9	4.9	26.7	19.5	26.0	11.3	28.8
11.0	26.3	11.0	26.4	10.7	26.6	6.4	25.8	23.2	26.3	14.0	29.0
12.8	26.2	14.0	26.6	15.2	26.8	8.2	25.7	24.4	27.0	18.9	29.3
14.3	26.2	17.7	26.5	27.1	26.6	12.5	27.0	30.5	27.2	20.7	29.1
17.7	26.2	26.2	26.3	33.5	26.4	18.3	27.1	42.7	27.3	26.8	29.3
19.5	26.3	28.0	26.2	40.2	26.2	26.8	27.1	54.3	27.3	28.0	28.3
30.5	26.4	30.5	26.2	43.3	26.2	33.8	26.9	58.8	27.1	32.6	27.7
45.7	26.5	34.4	26.2	45.1	26.3	36.6	26.9	59.7	26.9	36.6	27.6
61.0	26.7	35.7	26.3	48.5	26.4	43.0	26.8	62.2	26.8	39.6	27.9
66.4	26.8	39.3	26.4	51.8	26.5	46.6	26.8	63.4	26.9	41.1	27.6
76.2	27.3	53.6	26.9	57.3	26.6	51.5	26.8	64.6	26.8	46.3	27.6
97.8	27.4	64.0	27.1	70.1	26.9	60.4	26.6	67.1	26.8	47.5	26.4
100.3	27.6	73.2	27.4	71.9	27.1	64.3	26.4	68.0	26.7	51.8	26.6
100.6	27.9	88.4	27.7	80.5	27.4	68.3	26.5	72.8	26.8	53.9	26.5
104.9	28.2	104.9	27.9	97.5	27.9	72.8	26.6	79.2	26.7	54.3	26.7
115.8	28.1	107.6	28.3	112.8	28.0	75.6	26.5	82.6	26.5	55.2	27.3
130.5	28.2	111.3	27.9	124.4	28.0	77.4	26.5	85.3	26.5	62.2	27.4
143.3	28.4	115.8	28.3	138.4	28.1	79.6	26.6	89.3	26.5	65.2	27.8
152.4	28.3	132.9	28.1	149.4	28.3	81.7	26.7	93.6	26.5	73.2	27.9
157.9	28.3	152.4	28.0	165.2	28.6	89.0	26.9	99.7	26.7	76.2	27.6
160.3	27.7	160.9	28.0	170.7	28.2	92.4	27.3	106.1	26.9	88.4	27.6
167.6	27.7	163.4	27.9	192.9	28.5	100.3	27.4	108.8	27.3	100.6	27.4
189.0	27.6	170.4	27.9	229.2	28.1	102.4	27.7	116.1	27.4	104.2	27.2
198.7	27.9	172.8	28.1	231.0	30.0	112.8	27.9	118.3	27.7	108.5	27.0
215.2	28.0	179.8	28.2			137.2	28.2	132.6	28.0	110.6	27.2
222.5	27.6	190.2	28.3			139.0	28.0			112.8	27.2
226.8	27.6	204.2	28.0			146.3	28.2			114.9	27.1
228.9	29.8	213.1	28.1			152.4	28.4			115.8	27.2
		228.3	28.0			163.1	28.3			117.0	27.1
		230.1	29.8			164.6	28.6			118.6	27.1
						169.5	28.5			121.9	27.0
						170.1	28.7			123.7	26.9
						176.2	28.7			127.4	27.0
						177.1	28.4			130.5	26.9
						182.9	28.6			136.6	27.2
						204.2	28.5			137.2	27.3
						216.4	28.5			140.8	27.2
						226.2	28.4			146.3	27.1
						228.0	30.2			148.1	27.0
										150.3	27.2
										162.2	26.9
										173.4	27.8
										178.0	28.8







Figure 41A–F. Cross sections of channel, reach A, Santa Cruz River at Cortaro, Arizona, January 26, 1998. *A*, Transect A1. *B*, Transect A2. *C*, Transect A3. *D*, Transect A4. *E*, Transect A5. *F*, Transect A6. Local datum established as the zero point of the reference gage at streamflow-gaging station, Santa Cruz River at Cortaro, Arizona (09486500).

C. Transect A3







Figure 41A-F. Continued.






Figure 41A-F. Continued.

Table 36. Description and location of semipermanent monuments for reach A, Santa Cruz River at Cortaro, Arizona, January 26, 1996

Transect	Туре	Description of location and reference marks
A1	Left	Yellow painted line, 0.5 meter long on concrete about 18 meters upstream from tributary mouth on left bank. Reference-mark 1 is at gaging station.
A1	Right	Yellow painted line, 0.5 meter long on concrete about 18 meters upstream from tributary mouth on left bank.
A2	Left	Yellow painted line, 0.5 meter long on concrete about 70 meters upstream from transect A1.
A2	Right	Yellow painted line, 0.5 meter long on concrete about 70 meters upstream from transect A1.
A3	Left	Yellow painted line, 0.5 meter long on concrete about 54 meters upstream from transect A2.
A3	Right	Yellow painted line, 0.5 meter long on concrete about 54 meters upstream from transect A2.
A4	Left	Yellow painted line, 0.5 meter long on concrete about 38 meters upstream from transect A3.
A4	Right	Yellow painted line, 0.5 meter long on concrete about 38 meters upstream from transect A3.
A5	Left	Yellow painted line, 0.5 meter long on concrete about 78 meters upstream from transect A4.
A5	Right	Yellow painted line, 0.5 meter long on concrete about 78 meters upstream from transect A4.
A6	Left	Yellow painted line, 0.5 meter long on concrete about 57 meters upstream from transect A5.
A6	Right	Yellow painted line, 0.5 meter long on concrete about 57 meters upstream from transect A5.

Table 37. Habitat characteristics of reach A, Santa Cruz River at Cortaro, Arizona, January 23, 1996

[Embeddedness categories: 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment. NA, not applicable]

		Can	юру		Velocity		Sub	Substrate		
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness	
				Transec	ct 1 (Run)					
21.5	310	166	0	7.1	10.34	0.72	Gravel	Sand	5	
				3.5	.30	.54	Gravel	Sand	5	
				14.0	.15	.45	Gravel	Sand	5	
				Transec	ct 2 (Run)					
19.5	304	164	0	5.4	1.24	.81	Gravel	Sand	5	
				10.0	.24	.59	Gravel	Sand	5	
				15.0	.15	.73	Gravel	Sand	5	
				Transec	et 3 (Run)					
9.8	310	155	0	.4	.4	.49	Gravel	Sand	4	
				3.4	1.37	.27	Gravel	Sand	4	
				6.4	.34	.75	Gravel	Sand	4	
				Transec	t 4 (Riffle)					
7.7	312	151	0	.9	¹ .55	1.07	Gravel	NA	5	
				3.0	.52	.95	Gravel	NA	5	
				5.3	.18	.94	Gravel	Sand	4	
				Transec	t 5 (Riffle)					
7.8	276	170	3	6.6	¹ .64	1.05	Gravel	Sand	4	
				4.4	.27	.84	Gravel	Sand	4	
				2.2	.12	.45	Gravel	Sand	3	
				Transec	t 6 (Riffle)					
10.5	274	173	0	4.1	1.27	1.19	Gravel	Sand	5	
				6.2	.21	1.16	Gravel	Sand	4	
				7.3	.18	.86	Gravel	Sand	4	

¹Thalweg.




Figure 42. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, Santa Cruz River at Cortaro, Arizona, based on measurements made January 23, 1996.





Figure 43. Bed-material types at transects 1–6 and average for reach A, Santa Cruz River at Cortaro, Arizona, January 23, 1996.

Table 38. Density and dominance of woody vegetation for reach A, Santa Cruz River at Cortaro, Arizona, January 23, 1996
 [Length of reach, 297 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Tamarisk (<i>Tamarix sp.</i>)	4	2	8	40
Willow (Salix sp.)	3	2	25	60






Figure 44. Location of transects 1–6, reach A, Salt River near Roosevelt, Arizona.





Figure 45. Longitudinal profile, reach A, Salt River near Roosevelt, Arizona, July 27 and 28, 1998. Local datum established using arbitrary elevation.

Table 39. Cross-sectional survey data for reach A, Salt River near Roosevelt, Arizona, July 27 and 28, 1998 [All values are in meters. Distance is from left end point]

Trans	ect A1	Trans	ect A2	Trans	ect A3	Trans	ect A4	Trans	ect A5	Transect A6		
Distance	Elevation	Distance	Elevation									
0.0	15.1	0.6	12.7	0.6	16.9	2.6	14.7	0.0	19.9	87.9	17.0	
1.5	14.6	9.1	12.7	9.1	13.4	6.2	13.1	9.1	18.0	87.9	13.8	
15.2	13.9	15.2	12.5	22.3	12.5	15.2	13.4	10.7	16.8	86.0	13.1	
21.3	13.8	22.6	12.4	30.2	11.6	24.4	13.0	12.8	13.8	83.5	12.4	
36.6	13.4	23.5	12.2	36.6	11.2	27.4	12.6	15.2	13.1	82.3	12.1	
42.7	13.3	25.3	12.3	42.7	11.4	31.4	13.2	30.5	14.6	79.9	12.0	
45.1	12.9	27.4	12.1	48.8	11.7	33.5	13.1	39.6	14.9	78.0	12.2	
52.7	13.3	29.3	12.1	54.9	12.1	36.9	12.5	54.9	15.1	76.2	12.3	
61.9	12.4	32.9	12.0	57.6	12.4	44.2	12.1	64.0	15.1	73.2	12.7	
63.4	12.3	34.7	11.8	60.7	13.3	47.2	11.3	82.3	14.4	70.1	12.8	
64.0	12.4	36.6	11.8	62.8	13.1	51.8	11.3	94.5	13.6	64.0	12.5	
65.5	12.7	38.1	11.9	79.2	13.5	57.9	11.7	100.6	13.3	57.9	12.7	
68.0	12.4	39.6	11.8	83.2	13.3	67.1	11.9	107.6	12.7	52.7	13.2	
70.1	12.1	42.1	11.2	87.5	14.6	73.2	11.9	112.8	12.3	50.3	13.4	
71.9	12.4	43.3	11.0	90.8	16.3	83.8	12.4	115.8	12.0	46.3	13.6	
73.2	13.1	47.2	11.3	91.4	16.9	86.0	12.7	122.8	11.7	43.9	13.7	
76.2	12.8	49.1	11.9			88.4	13.4	128.0	12.7	36.6	13.7	
79.2	12.6	50.0	12.8			90.2	13.4	131.1	12.9	34.0	13.2	
83.5	12.6	57.9	12.9			93.3	15.8	140.1	17.2	30.2	12.7	
85.3	12.3	65.8	12.9			96.3	15.8			27.1	13.2	
88.4	12.1	68.6	13.0			98.1	17.3			21.0	14.2	
91.4	12.1	71.3	13.0			99.1	17.8			21.0	14.2	
94.5	11.9	74.4	12.9							17.1	14.3	
97.5	12.1	78.6	13.1							13.4	14.5	
101.5	12.3	81.1	13.6							10.4	14.4	
102.1	12.4									6.1	16.0	
112.8	12.6									1.8	16.0	
118.9	12.1									.8	16.4	
120.7	11.3											
122.5	10.8											
124.4	10.5											
125.6	10.2											
132.3	10.3											
132.9	10.9											
132.9	15.0											







Figure 46A–F. Cross sections of channel, reach A, Salt River near Roosevelt, Arizona, July 27 and 28, 1998. *A*, Transect A1. *B*, Transect A2. *C*, Transect A3. *D*, Transect A4. *E*, Transect A5. *F*, Transect A6. Local datum established using arbitrary elevation.







Figure 46A-F. Continued.






Figure 46A-F. Continued.

Table 40. Description and location of semipermanent monuments for reach A, Salt River near Roosevelt, Arizona, July 27 and 28, 1998

Transect	Туре	Description of location and reference marks						
A1	Left	Rebar.						
A1	Right	Rebar at base of rock cliff.						
A2	Left	Rebar, 175 meters upstream from transect A1.						
A2	Right	Rebar, 175 meters upstream from transect A1.						
A3	Left	Lone boulder about 20 meters upstream from boat ramp.						
A3	Right	Chiseled square in boulder at base of bluff about 20 meters upstream from boat ramp.						
A4	Left	Chiseled square in bedrock outcrop at base of cliff, 145 meters upstream from right bank of transect A3.						
A4	Right	Large eyebolt in rock, 78 meters upstream from transect A3.						
A5	Left	Rebar, 100 meters upstream from transect A4.						
A5	Right	Rebar, 100 meters upstream from transect A4.						
A6	Left	Rebar in rock cliff, 125 meters upstream from transect A5.						
A6	Right	Rebar in rock cliff, 125 meters upstream from transect A5.						

Table 41. Habitat characteristics of reach A, Salt River near Roosevelt, Arizona, December 13, 1995

[Embeddedness categories: 0, no gravel, cobbles, or boulders present; 2, 51 to 75 percent covered by fine sediment; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment. Dashes indicate no data. NA, not applicable]

		Canopy			Velocity		Sub	strate	
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness
				Tra	nsect 1 (Run)				
61.6	320	144	26	28.0	0.43	1.55	Cobble	Gravel	3
				31.0	.40	.45	Cobble	Gravel	3
				46.0	.70	.41	Gravel	Cobble	4
				52.0	.61	.43	Cobble	Gravel	
				61.5	11.04	² .01	Silt	Sand	0
				Trai	nsect 2 (Riffle)				
23.0	358	158	0	1.5	.09	.12	Cobble	Gravel	3
				18.4	.30	.79	Cobble	NA	3
				22.6	1.43	1.69	Cobble	NA	
				Tra	nsect 3 (Pool)				
40.3	310	138	0	11.6	11.07	.22	Sand	Cobble	3
				20.0	.66	.28	Sand	NA	0
				30.0	.79	.19	Sand	NA	0
				Tra	nsect 4 (Pool)				
62.0	254	155	0	12.8	11.00	.24	Silt	Sand	0
				30.0	.62	.25	Silt	Sand	0
				40.0	.33	.20	Silt	Sand	0
				Tra	nsect 5 (Run)				
20.6	272	136	25	5.0	.52	.56	Boulder	Cobble	2
				9.5	1.98	.36	Boulder	Sand	2
				14.2	.97	.92	Boulder	Sand	2
				Trai	nsect 6 (Riffle)				
55.8	302	102	12	30.6	.27	.26	Sand	Silt	0
				40.4	.27	.57	Sand	Cobble	2
				50.1	¹ .94	.58	Sand	Gravel	5

¹Thalweg. ²Reverse flow.




Figure 47. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, Salt River near Roosevelt, Arizona, based on measurements made December 13, 1995.




Figure 48. Bed-material types at transects 1–6 and average by reach A, Salt River near Roosevelt, Arizona, December 13, 1995.

Table 42. Density and dominance of woody vegetation for reach A, Salt River near Roosevelt, Arizona, December 13, 1995 [Length of reach, 610 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Mesquite (Prosopis sp.)	452	9	8	6
Tamarisk (<i>Tamarix sp.</i>)	37	8	58	81
Willow (Salix sp.)	54	2	17	12






Figure 49. Location of transects 1–6, reach A, Verde River above West Clear Creek, near Camp Verde, Arizona.





Figure 50. Longitudinal profile, reach A, Verde River above West Clear Creek, near Camp Verde, Arizona, December 1 and 5, 1997. Local datum established using arbitrary elevation.

A. Transect A1







Figure 51A-F. Cross sections of channel, reach A, Verde River above West Clear Creek, near Camp Verde, Arizona, December 1 and 5, 1997. A, Transect A1. B, Transect A2. C, Transect A3. D, Transect A4. E, Transect A5. F, Transect A6. Local datum established using arbitrary elevation.







Figure 51A-F. Continued.






Figure 51A-F. Continued.

Table 43. Cross-sectional survey data for reach A, Verde River above West Clear Creek, near Camp Verde, Arizona, December 1 and 5, 1997

[All values are in meters. Distance is from left end point]

Transe	Transect A1		ect A2	Transect A3		Transect A4		Trans	ect A5	Transect A6	
Distance	Elevation	Distance	Elevation	Distance	Elevation	Distance	Elevation	Distance	Elevation	Distance	Elevation
0.0	154.5	0.0	155.1	0.0	156.2	0.0	154.8	0.0	155.6	0.0	153.7
4.9	153.9	0.0	154.8	6.1	156.5	7.3	152.4	1.8	155.6	5.8	153.4
6.1	154.1	11.3	154.6	21.3	154.7	10.7	152.0	4.9	154.3	5.8	152.5
8.2	154.3	15.5	153.4	25.0	153.6	13.7	152.2	16.5	152.4	9.8	152.3
10.1	153.6	34.1	153.2	26.8	154.0	22.3	151.4	18.3	151.3	16.5	152.9
11.6	153.1	40.8	151.9	32.0	152.8	23.8	151.1	22.9	151.1	18.6	152.2
17.4	152.9	47.5	152.2	37.8	152.5	25.6	150.9	23.5	150.8	21.6	151.8
20.1	152.9	56.1	152.5	40.5	152.8	28.7	150.5	25.6	150.7	22.6	151.3
27.1	153.3	59.1	152.7	46.3	152.2	32.3	150.3	28.0	150.6	23.5	151.2
39.6	152.5	61.9	152.4	52.1	151.9	36.3	150.3	29.0	150.6	25.6	151.0
43.9	152.6	69.8	152.0	55.2	151.4	41.1	150.3	29.3	151.1	28.7	151.0
47.2	152.3	90.2	151.1	58.8	151.2	44.8	150.3	30.5	151.2	31.1	151.1
51.8	152.4	99.4	151.1	67.1	150.8	47.2	150.6	33.5	152.1	32.3	151.2
57.9	152.3	115.8	150.7	68.6	150.5	48.8	150.6	36.6	152.1	32.9	151.3
70.4	152.4	121.9	150.5	72.2	150.3	50.3	150.8	39.0	151.3	38.4	152.0
76.8	152.3	133.5	150.2	74.1	150.2	51.2	150.8	44.8	151.1	41.5	151.9
91.4	151.5	135.0	150.1	76.2	150.2	52.7	150.6	45.7	150.9	43.3	152.2
99.4	151.4	136.2	149.9	83.5	150.4	54.9	150.6	50.0	150.6	45.1	151.8
101.8	151.4	137.8	149.8	89.0	150.5	56.4	150.6	54.9	150.5	48.5	151.8
106.1	151.2	140.8	149.7	91.7	150.5	59.7	150.6	61.6	150.5	52.1	152.1
123.1	150.9	145.7	149.7	93.3	150.9	62.5	150.9	65.2	150.6	53.3	152.3
127.7	150.8	147.2	149.6	96.9	150.9	66.4	151.1	67.1	150.7	54.6	152.4
141.1	150.3	148.7	149.6	99.4	150.8	72.5	151.1	70.7	150.7	59.1	151.8
149.0	149.7	150.6	149.8	102.1	150.7	79.9	151.4	73.5	150.7	64.0	151.6
154.8	149.5	151.8	150.1	105.2	150.7	82.6	151.5	77.1	150.9	68.0	151.8
157.6 165.5	149.6 149.4	154.8 156.1	150.2	108.8 116.1	150.7 150.9	84.7	152.0	84.4 96.0	151.4	73.8 74.4	151.7 150.9
			150.5			89.6	152.0		152.6		
169.8	149.2 149.0	157.0 164.3	150.5 150.7	118.3 123.7	150.9	95.4 96.9	152.7	104.2 108.2	152.2	75.9 78.3	150.3 150.4
169.8 171.9	149.0	167.3	150.7	125.7	150.5 150.1	102.1	152.5 152.8	111.3	152.5 152.9	80.2	150.4
174.3	148.5	171.0	149.9	126.8	150.1	107.3	152.7	111.5	153.3	82.3	151.0
174.3	148.4	171.0	149.5	120.8	150.1	107.3	132.7	110.0	155.5	90.2	151.4
177.7	148.7	173.7	150.1	127.7	151.5					94.2	151.4
177.7	149.0	205.7	151.4	142.0	152.3					96.9	151.0
181.7	149.2	208.2	152.7	142.0	132.3					100.3	151.1
182.6	149.2	200.2	132.7							104.5	151.3
183.5	149.6									108.8	151.1
189.6	149.9									111.6	151.5
195.1	150.4									118.9	151.8
199.3	151.1									119.8	151.6
202.4	154.1									126.2	151.6
										139.6	151.8
										155.4	151.9
										163.1	153.1
										171.3	152.8
										186.5	152.4
										188.1	151.2
										197.2	152.5
										200.9	153.3

Table 44. Description and location of semipermanent monuments for reach A, Verde River above West Clear Creek near Camp Verde, Arizona, December 1 and 5, 1997

Transect	Туре	Description of location and reference marks
A1	Left	Rebar. Reference-mark 1 is nail in streamward side of cottonwood tree at transect A2. Elevation is
		153.21 meters local datum.
A1	Right	Rebar at foot bridge over canal at rest stop.
A2	Left	Rebar, 80 meters upstream from canal bridge in bedrock slope.
A2	Right	Rebar, 80 meters upstream from transect A1.
A3	Left	Rebar about 25 meters upstream from two railroad ties in fence line.
A3	Right	Rebar, 120 meters upstream from transect A2.
A4	Left	Rebar, 85 meters upstream from transect A3.
A4	Right	Rebar, 85 meters upstream from transect A3.
A5	Left	Rebar, 107 meters upstream from transect A4.
A5	Right	Rebar, 107 meters upstream from transect A4.
A6	Left	Rebar, 75 meters upstream from transect A5.
A6	Right	Rebar, 75 meters upstream from transect A5.

Table 45. Habitat characteristics of reach A, Verde River above West Clear Creek, near Camp Verde, Arizona, October 24, 1995 [Embeddedness categories: 2, 51 to 75 percent covered by fine sediment; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment]

		Canopy			Velocity		Sub	strate	
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge Velocity, of water, Depth, in meters in meters in meters per second		Dominant	Subdominant	Embeddedness	
				Tran	nsect 1 (Run)				
14.0	124	149	0	3.2	0.39	0.41	Cobble	Sand	3
				7.5	¹ .77	.97	Boulder	Cobble	4
				10.7	.24	.08	Cobble	Boulder	3
				Tran	sect 2 (Riffle)				
18.3	173	165	0	4.0	.35	.63	Cobble	Gravel	4
				8.2	.26	.87	Cobble	Boulder	3
				12.4	¹ .50	.70	Cobble	Gravel	2
				Trar	sect 3 (Pool)				
58.4	166	158	15	7.8	1.63	.45	Gravel	Sand	3
				14.0	.47	.25	Gravel	Cobble	2
				20.0	.28	.06	Gravel	Cobble	3
				43.2	.23	.11	Gravel	Cobble	2
				Tran	nsect 4 (Run)				
45.6	168	153	0	4.0	1.58	.21	Gravel	Cobble	5
				17.0	.30	.22	Gravel	Cobble	4
				30.0	.32	.19	Gravel	Cobble	4
				Tran	sect 5 (Run)				
57.4	167	162	24	8.8	.32	1.00	Cobble	Gravel	4
				37.1	¹ .48	.33	Gravel	Cobble	2
				43.0	.41	.19	Gravel	Cobble	3
				49.0	.11	.30	Gravel	Cobble	3
				Tran	sect 6 (Riffle)				
124.0	151	146	0	3.0	1.73	.44	Cobble	Gravel	4
				69.8	.42	.54	Cobble	Gravel	4
				87.3	.24	.53	Cobble	Boulder	4
				105.7	.16	.17	Cobble	Sand	4

¹Thalweg.




Figure 52. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, Verde River above West Clear Creek, near Camp Verde, Arizona, based on measurements made October 24, 1995.





Figure 53. Bed-material types at transects 1–6 and average for reach A, Verde River above West Clear Creek, near Camp Verde, Arizona, October 24, 1995.

Table 46. Density and dominance of woody vegetation for reach A, Verde River above West Clear Creek, near Camp Verde, Arizona, October 24, 1995

[Length of reach, 467 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Arizona alder (Alnus oblongifolia)	133	3	8	3
Arizona sycamore (Plantanus wrightii)	440	35	25	14
Fremont cottonwood (Populus fremontii)	2,107	379	50	31
Mesquite (Prosopis sp.)	113	5	8	7
Tamarisk (Tamarix sp.)	16	2	42	24
Willow (Salix sp.)	15	2	25	21








Figure 54. Location of transects 1–6, reaches A–C, West Clear Creek near Camp Verde, Arizona.





Figure 55. Longitudinal profile, reach A, West Clear Creek near Camp Verde, Arizona, December 3 and 4, 1997. Local datum established using arbitrary elevation.

Table 47. Cross-sectional survey data for reach A, West Clear Creek near Camp Verde, Arizona, December 3 and 4, 1997 [All values are in meters. Distance is from left end point]

Trans	ect A1	Trans	ect A2	Trans	ect A3	Trans	ect A4	Trans	ect A5	Trans	ect A6
Distance	Elevation										
0.0	151.4	0.0	152.9	0.0	153.2	0.0	153.4	0.0	152.2	0.0	154.1
2.7	150.9	2.4	151.5	2.1	152.4	1.2	152.9	3.7	151.7	4.9	152.8
7.3	150.4	6.1	151.0	4.9	151.7	3.4	152.3	7.6	151.1	5.8	152.6
9.1	149.6	11.9	151.0	7.0	151.3	5.5	151.7	9.1	150.7	6.7	152.7
10.4	149.4	13.1	150.6	8.2	151.0	7.6	151.2	10.7	150.3	16.2	152.7
12.2	149.2	13.7	149.6	9.1	150.9	8.8	151.0	13.4	150.4	19.2	151.5
15.2	149.2	15.2	149.5	10.1	150.5	10.1	150.7	15.2	150.4	20.4	151.4
16.8	149.0	17.4	149.5	10.4	149.9	12.2	150.5	17.1	150.5	22.6	150.8
18.0	149.3	19.2	149.6	11.3	149.9	15.2	150.2	19.8	150.6	24.1	150.6
20.1	149.3	21.0	149.6	12.8	149.9	16.5	150.3	21.9	150.6	25.6	150.4
23.5	149.6	22.6	149.6	14.3	149.8	18.6	150.5	25.0	150.5	27.7	150.4
27.7	149.6	23.8	149.8	15.8	149.9	21.3	150.3	27.4	150.7	28.7	150.4
31.7	150.0	24.7	150.0	17.1	150.0	23.5	150.4	30.8	150.3	29.9	150.3
37.2	150.2	25.9	149.8	18.3	150.2	26.5	150.7	33.5	150.6	31.4	150.3
42.7	149.6	27.4	149.8	19.8	150.4	32.0	150.8	35.1	151.3	33.2	150.3
47.2	148.7	30.8	149.8	20.7	150.4	35.1	151.3	36.9	151.2	34.7	150.6
49.4	149.4	34.1	149.7	21.3	150.3	36.9	151.8	41.5	151.6	35.8	150.8
52.4	150.1	36.0	149.9	23.5	150.4	38.1	151.7			36.9	151.3
54.9	151.1	37.5	150.7	28.3	150.6	45.4	151.5			37.5	152.2
		40.2	150.9	31.4	150.7	47.4	152.5			39.3	152.4
		43.0	150.4	36.3	151.2					41.1	152.9
		47.2	150.4	39.0	151.0					43.0	153.3
		52.4	151.1	41.5	151.3						
		53.6	151.9	43.9	152.1						
				50.0	152.5						







Figure 56A–F. Cross sections of channel, reach A, West Clear Creek, near Camp Verde, Arizona, December 3 and 5, 1997. *A*, Transect A1. *B*, Transect A2. *C*, Transect A3. *D*, Transect A4. *E*, Transect A5. *F*, Transect A6. Local datum established using arbitrary elevation.







Figure 56A-F. Continued.






Figure 56A–F. Continued.

Table 48. Description and location of semipermanent monuments for reach A, West Clear Creek near Camp Verde, Arizona, December 3 and 4, 1997

Transect	Туре	Description of location and reference marks
A1	Left	Rebar, about 75 meters upstream from gaging station. Reference-mark 1 is rebar painted white at base of cliff about 75 meters upstream from gaging station. Established in 1995. Elevation is 154.37 meters.
A1	Right	Rebar, about 75 meters upstream from gaging station.
A2	Left	Rebar, 55 meters upstream from transect A1.
A2	Right	Rebar, 55 meters upstream from transect A1.
A3	Left	Rebar, about 40 meters upstream from transect A2.
A3	Right	Rebar, 40 meters upstream from transect A2.
A4	Left	Rebar, 29 meters upstream from transect A3.
A4	Right	Rebar, 29 meters upstream from transect A3.
A5	Left	Rebar, 45 meters upstream from transect A4.
A5	Right	Rebar, 45 meters upstream from transect A4.
A6	Left	Rebar, 38 meters upstream from transect A5.
A6	Right	Rebar, 38 meters upstream from transect A5.

Table 49. Habitat characteristics of reach A, West Clear Creek near Camp Verde, Arizona, October 11, 1995

[Embeddedness categories: 1, more than 75 percent covered by fine sediment; 2, 51 to 75 percent covered by fine sediment; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment]

		Canopy			Velocity		Sub		
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness
				Transe	ect 1 (Riffle)				
10.1	283	110	21	3.8	10.31	0.50	Cobble	Gravel	1
				5.8	.22	.72	Cobble	Gravel	3
				8.1	.15	.22	Cobble	Gravel	3
				Transe	ect 2 (Riffle)				
23.0	278	63	65	2.4	1.36	.30	Boulder	Cobble	3
				5.2	.24	.20	Boulder	Gravel	3
				8.0	.26	.09	Cobble	Gravel	3
				19.4	.20	.16	Boulder	Cobble	2
				Transe	ect 3 (Riffle)				
19.3	284	56	41	2.5	.20	.19	Boulder	Cobble	2
				6.9	1.34	1.02	Boulder	Cobble	3
				8.5	.27	.33	Boulder	Cobble	3
				15.3	.16	.08	Cobble	Boulder	3
				Transe	ect 4 (Riffle)				
15.7	277	86	25	3.4	1.38	.38	Boulder	Cobble	2
				7.4	.11	.55	Boulder	Gravel	3
				11.4	.17	.12	Cobble	Boulder	3
				Trans	ect 5 (Run)				
18.7	275	103	13	2.6	.39	.06	Cobble	Boulder	4
				6.3	1.48	.19	Cobble	Boulder	3
				13.3	.16	.08	Cobble	Gravel	4
				Trans	ect 6 (Run)				
12.8	267	94	19	3.4	.37	.25	Boulder	Cobble	3
				6.7	1.52	.17	Cobble	Gravel	2
				9.0	.49	.16	Boulder	Cobble	4

¹Thalweg.




Figure 57. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, West Clear Creek near Camp Verde, Arizona, based on measurements made October 11, 1995.




Figure 58. Bed-material types at transects 1–6 and average for reach A, West Clear Creek near Camp Verde, Arizona, October 11, 1995.

Table 50. Density and dominance of woody vegetation for reach A, West Clear Creek near Camp Verde, Arizona, October 11, 1995 [Length of reach, 207 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Arizona alder (Alnus oblongifolia)	602	602	50	21
Arizona sycamore (Plantanus wrightii)	612	704	58	24
Box elder (Acer negundo)	548	132	17	5
Fremont cottonwood (Populus fremontii)	1,980	475	17	5
Juniper (Juniperus sp.)	350	200	33	12
Silverleaf oak (Quercus hypoleucoides)	855	86	8	2
Velvet ash (Fraxinus velutina)	334	494	75	31

Table 51. Habitat characteristics of reach A, West Clear Creek near Camp Verde, Arizona, October 24, 1996

[Embeddedness categories: 1, more than 75 percent covered by fine sediment; 2, 51 to 75 percent covered by fine sediment; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment. <, less than]

		Can	пору		Velocity		Sul	bstrate	
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	of water, Depth, in mete		Velocity, in meters per second	Dominant Subdominant		Embeddedness
				Trai	nsect 1 (Riffle)				
10.9	279	114	40	2.0	0.18	0.12	Cobble	Gravel	3
				4.2	.24	.23	Cobble	Gravel	1
				7.0	¹ .36	.53	Boulder	Cobble	3
				Trai	nsect 2 (Riffle)				
22.3	274	34	69	4.2	1.40	.24	Boulder	Cobble	2
				5.7	.21	.05	Gravel	Boulder	5
				8.7	.24	.27	Boulder	Cobble	2
				18.9	.18	.16	Cobble	Silt	3
				Trai	nsect 3 (Riffle)				
18.2	264	49	78	1.1	.21	.10	Gravel	Cobble	5
				2.7	.21	.05	Cobble	Silt	3
				4.2	.18	.46	Boulder	Cobble	3
				6.0	1.40	.41	Boulder	Gravel	2
				Trans	sect 4 (Riffle)				
14.1	269	70	26	2.3	1.36	.47	Boulder	Cobble	4
				5.1	.27	.69	Boulder	Cobble	4
				9.3	.21	.29	Cobble	Boulder	3
				Tran	sect 5 (Run)				
18.5	259	82	25	5.1	1.52	.20	Cobble	Gravel	3
				9.4	.30	.06	Cobble	Boulder	2
				13.7	.15	<.01	Cobble	Boulder	3
				Tran	sect 6 (Run)				
13.1	275	119	10	2.4	.40	.22	Boulder	Cobble	4
				6.1	¹ .61	.13	Cobble	Gravel	3
				9.0	.58	.06	Gravel	Boulder	2

¹Thalweg.




Figure 59. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, West Clear Creek near Camp Verde, Arizona, based on measurements made October 24, 1996.




Figure 60. Bed-material types at transects 1–6 and average for reach A, West Clear Creek near Camp Verde, Arizona, October 24, 1996.




Figure 61. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach B, West Clear Creek near Camp Verde, Arizona, based on measurements made October 31, 1996.




Figure 62. Bed-material types at transects 1–6 and average for reach B, West Clear Creek near Camp Verde, Arizona, October 31, 1996.

Table 52. Density and dominance of woody vegetation for reach B, West Clear Creek near Camp Verde, Arizona, October 24, 1996 [Length of reach, 210 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Arizona alder (Alnus oblongifolia)	477	334	42	15
Arizona sycamore (Plantanus wrightii)	1,023	951	58	20
Boxelder (Acer negundo)	28	3	8	2
Fremont cottonwood (Populus fremontii)	3,632	436	8	2
Juniper (Juniperus sp.)	350	176	33	12
Netleaf hackberry (Celtis reticulata)	88	20	17	5
Oak (Quercus sp.)	13	2	8	2
Single leaf piñon (Pinus monophylla)	177	21	8	2
Velvet ash (Fraxinus velutina)	242	424	92	38

Table 53. Habitat characteristics of reach B, West Clear Creek near Camp Verde, Arizona, October 31, 1996

[Embeddedness categories 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment]

		Can	ору	Velocity			Sul		
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness
				Tran	sect 1 (Riffle)				
34.2	239	96	43	1.0	0.20	1.03	Boulder	Cobble	4
				2.0	.30	1.11	Boulder	Cobble	4
				26.0	.24	.08	Boulder	Cobble	3
				31.0	1.34	.08	Boulder	Cobble	5
				Trai	nsect 2 (Run)				
13.1	225	97	29	4.1	1.46	.15	Boulder	Gravel	4
				7.4	.24	.12	Boulder	Cobble	4
				10.3	.30	.30	Gravel	Boulder	4
				Trai	nsect 3 (Pool)				
21.1	255	103	24	4.2	.15	.25	Gravel	Cobble	5
				9.8	.55	.09	Cobble	Gravel	3
				15.6	¹ .98	.02	Gravel	Cobble	3
				Tran	sect 4 (Riffle)				
9.8	314	92	26	2.0	.24	.26	Boulder	Cobble	4
				4.6	1.46	.45	Boulder	Cobble	3
				7.1	.27	.39	Boulder	Cobble	5
				Tran	sect 5 (Riffle)				
11.4	326	136	22	3.1	.21	.43	Boulder	Cobble	4
				6.0	1.40	.57	Cobble	Boulder	5
				9.0	.30	.21	Boulder	Cobble	4
				Tran	sect 6 (Riffle)				
16.9	332	140	3	6.1	1.34	.12	Boulder	Cobble	4
				11.5	.34	.10	Boulder	Cobble	4
				13.9	.24	.71	Boulder	Cobble	5

¹Thalweg.

Table 54. Density and dominance of woody vegetation for reach C, West Clear Creek near Camp Verde, Arizona, October 31, 1996 [Length of reach, 319 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Arizona alder (Alnus oblongifolia)	140	97	75	40
Arizona sycamore (Plantanus wrightii)	432	173	58	23
Juniper (Juniperus sp.)	234	28	25	7
Mesquite (<i>Prosopis sp.</i>)	133	4	8	2
Netleaf hackberry (Celtis reticulata)	18	1	17	5
Single leaf piñon (Pinus monophylla)	538	43	8	5
Velvet ash (Fraxinus velutina)	266	64	33	14
Willow (Salix sp.)	10	1	17	5

Table 55. Habitat characteristics of reach C, West Clear Creek near Camp Verde, Arizona, November 6, 1996

[Embeddedness categories: 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment]

		Can	юру		Velocity		Sul		
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness
				Trans	sect 1 (Riffle)				
13.8	256	81	37	3.8	0.09	0.29	Cobble	Boulder	3
				8.4	1.32	.41	Boulder	Cobble	3
				12.5	.27	.76	Boulder	Cobble	3
				Tran	sect 2 (Run)				
14.7	260	98	44	4.2	.08	0	Boulder	Cobble	3
				8.2	.42	.26	Boulder	Gravel	3
				12.8	¹ .59	.08	Boulder	Gravel	4
				Tran	sect 3 (Run)				
15.0	257	78	29	3.4	.15	.12	Cobble	Boulder	4
				6.8	1.46	.20	Boulder	Cobble	4
				11.1	.27	.01	Cobble	Boulder	4
				Trans	sect 4 (Riffle)				
14.1	254	108	16	2.4	.12	.40	Boulder	Cobble	4
				4.7	1.36	.44	Boulder	Cobble	5
				8.8	.15	.14	Cobble	Boulder	4
				Transe	ect 5 (Riffle)				
15.7	256	85	28	4.0	¹ .34	.50	Cobble	Gravel	4
				8.5	.12	.39	Cobble	Gravel	4
				12.2	.12	.02	Cobble	Boulder	4
					ect 6 (Riffle)				
9.3	259	106	3	2.3	.37	.17	Boulder	Cobble	4
				4.4	.26	.72	Boulder	Cobble	5
				6.5	¹ .49	.10	Boulder	Cobble	5

¹Thalweg.




Figure 63. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach C, West Clear Creek near Camp Verde, Arizona, based on measurements made November 6, 1996.




Figure 64. Bed-material types at transects 1–6 and average for reach C, West Clear Creek near Camp Verde, Arizona, November 6, 1996.

 Table 56.
 Density and dominance of woody vegetation for reach C, West Clear Creek near Camp Verde, Arizona, November 6, 1996
 [Length of reach, 121 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Arizona alder (Alnus oblongifolia)	762	632	50	22
Arizona sycamore (Plantanus wrightii)	760	372	33	13
Boxelder (Acer negundo)	305	46	17	4
Mesquite (<i>Prosopis sp.</i>)	50	4	8	2
Mulberry (Morus sp.)	38	3	8	2
Netleaf hackberry (Celtis reticulata)	38	3	8	2
Juniper (Juniperus sp.)	137	93	50	18
Velvet ash (Fraxinus velutina)	187	252	67	36

 Table 57.
 Habitat characteristics of reach A, West Clear Creek near Camp Verde, Arizona, November 6, 1997

[Embeddedness categories: 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment]

		Canopy		Velocity			Sul		
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness
				Tra	ansect 1 (Riffle	e)			
10.0	284	125	56	2.4	0.15	0.64	Cobble	Boulder	4
				5.7	1.34	.60	Cobble	Boulder	4
				8.0	.12	.29	Boulder	Cobble	4
				Tra	ansect 2 (Riffle	e)			
21.0	278	52	81	2.8	1.30	.07	Cobble	Boulder	4
				6.2	.24	.46	Cobble	Boulder	4
				9.2	.23	.32	Cobble	Boulder	4
				19.5	.15	.19	Cobble	Gravel	3
				Tra	ansect 3 (Riffle	e)			
18.6	266	50	98	2.0	.27	.08	Gravel	Boulder	5
				6.5	¹ .36	.43	Cobble	Gravel	4
				8.4	.34	.39	Boulder	Cobble	4
				15.2	.15	.05	Gravel	Cobble	4
				Trai	nsect 4 (Riffle)				
15.0	263	84	37	5.5	1.36	.58	Cobble	Gravel	4
				9.0	.09	.09	Boulder	Cobble	4
				12.5	.24	.15	Boulder	Cobble	4
				Tra	nsect 5 (Run)				
19.1	255	67	50	4.1	1.43	.24	Boulder	Gravel	4
				9.5	.27	.34	Cobble	Boulder	4
				15.0	.12	.13	Cobble	Gravel	4
				Tra	nsect 6 (Run)				
11.7	258	115	48	3.0	.35	.18	Cobble	Gravel	4
				5.0	.46	.19	Cobble	Gravel	3
				8.5	¹ .49	.12	Gravel	Cobble	5

¹Thalweg.




Figure 65. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, West Clear Creek near Camp Verde, Arizona, based on measurements made November 6, 1997.




Figure 66. Bed-material types at transects 1–6 and average for reach A, West Clear Creek near Camp Verde, Arizona, November 6, 1997.

Table 58. Density and dominance of woody vegetation for reach A, West Clear Creek near Camp Verde, Arizona, November 6, 1997 [Length of reach, 249 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Arizona alder (Alnus oblongifolia)	225	720	75	48
Arizona sycamore (Plantanus wrightii)	120	80	17	10
Fremont cottonwood (Populus fremontii)	20	4	8	3
Netleaf hackberry (Celtis reticulata)	95	19	8	3
Velvet ash (Fraxinus velutina)	318	741	58	35






Figure 67. Location of transects 1–6, reach A, Verde River below Tangle Creek, above Horseshoe Dam, Arizona.





Figure 68. Longitudinal profile, reach A, Verde River below Tangle Creek, above Horseshoe Dam, Arizona, July 29, 1998. Local datum established using arbitrary elevation.

Table 59. Cross-sectional survey data for reach A, Verde River below Tangle Creek, above Horseshoe Dam, Arizona, July 29, 1998 [All values are in meters. Distance is from left end point]

Trans	Transect A1		Transect A2		Transect A3		Transect A4		ect A5	Transect A6	
Distance	Elevation	Distance	Elevation	Distance	Elevation	Distance	Elevation	Distance	Elevation	Distance	Elevation
0.0	16.2	0.0	16.0	0.0	16.5	0.0	15.7	0.0	15.8	0.0	14.3
2.1	15.7	1.8	15.5	2.7	15.6	9.1	15.4	4.3	15.7	8.5	13.0
4.3	15.6	3.4	14.9	3.4	15.1	18.3	14.9	9.1	12.4	13.1	12.0
6.7	14.5	9.1	15.1	15.8	15.3	25.0	12.5	12.2	11.7	14.0	11.8
12.8	14.4	15.2	15.1	23.5	15.4	26.2	12.1	15.2	11.7	14.3	11.4
17.1	14.3	24.4	15.1	31.1	15.2	28.7	11.9	18.3	11.7	15.8	11.3
21.3	14.6	29.3	15.2	39.9	14.9	31.1	11.8	21.3	11.8	18.3	11.4
27.4	15.2	33.5	14.9	46.3	14.5	33.5	11.7	24.4	11.9	21.3	11.5
34.4	15.9	39.6	14.1	50.0	12.5	39.6	11.6	30.5	11.9	24.4	11.4
37.2	15.6	42.7	14.1	52.4	12.0	45.7	11.8	39.6	12.2	27.4	11.5
40.2	15.8	43.9	13.9	56.1	11.7	51.8	11.7	43.3	12.2	29.6	11.6
44.5	15.9	46.6	12.5	57.0	11.6	57.9	11.7	47.2	12.1	31.7	11.7
50.0	15.6	48.8	12.0	61.6	11.5	61.0	11.9	51.8	12.4	34.4	11.7
53.6	15.6	52.7	11.8	66.4	11.6	64.6	12.5	54.9	12.8	37.8	11.7
61.0	13.3	53.6	11.5	68.3	11.8	69.5	13.5	57.9	12.6	41.5	11.7
65.2	13.4	57.9	11.5	70.7	12.1	77.7	13.5	65.5	13.0	45.1	11.9
65.8	13.6	61.0	11.7	73.2	12.2	78.6	14.1	70.7	13.6	48.8	12.0
68.9	13.5	67.1	11.8	73.8	12.1	79.6	14.4	84.4	14.0	53.3	12.2
71.9	13.7	70.1	11.9	76.5	12.5	83.2	14.4	86.6	13.8	56.1	12.1
74.4	13.6	71.9	12.1	77.1	12.5	85.0	14.3	91.4	14.1	60.0	12.2
78.0	13.7	75.6	13.0	77.4	12.5	86.3	13.7	98.1	14.4	62.2	12.3
79.9	13.5	77.7	12.5	78.9	12.3	91.4	13.9	101.2	14.6	65.2	12.5
82.9	13.3	81.1	13.1	81.4	12.5	94.8	13.8	105.5	15.1	73.2	12.8
86.6	13.8	83.5	13.4	84.7	12.7	97.8	14.0	108.2	14.9	77.7	13.1
86.9	14.1	86.3	13.1	87.2	12.9	102.1	14.0	110.6	14.9	82.9	13.2
89.9	14.3	88.4	14.1	96.3	13.7	105.2	14.7	112.5	15.1	86.3	13.0
94.5	14.4	92.0	14.1	101.2	13.7	107.3	14.9	117.0	15.7	91.4	13.0
95.7	14.1	95.1	15.6	106.7	14.0					103.3	13.1
98.5	14.6	99.4	16.0	110.0	13.7						
100.9	14.4	105.2	16.0	114.3	14.0						
107.0	14.4	106.4	16.4	118.0	14.1						
107.3	15.0	109.7	14.7	122.5	14.5						
		113.4	14.2	124.4	15.0						
		117.0	14.0	125.9	15.8						
		119.5	15.3								
		121.0	16.3								
		123.1	15.4								
		126.2	15.7								
		128.9	17.8								
		129.5	17.4								







Figure 69A–F. Cross sections of channel, reach A, Verde River below Tangle Creek, above Horseshoe Dam, Arizona, July 29, 1998. *A*, Transect A1. *B*, Transect A2. *C*, Transect A3. *D*, Transect A4. *E*, Transect A5. *F*, Transect A6. Local datum established using arbitrary elevation.






Figure 69A-F. Continued.

E. Transect A5 ELEVATION RELATIVE TO LOCAL DATUM, IN METERS Land Surface ── Water Surface

DISTANCE FROM LEFT END POINT, IN METERS




Figure 69A-F. Continued.

Table 60. Description and location of semipermanent monuments for reach A, Verde River below Tangle Creek, above Horseshoe Dam, Arizona, July 29, 1998

Transect	Туре	Description of location and reference marks
A1	Left	Rebar. Reference-mark 1 is cable anchor on left side of Sheeps Bridge. Reference-mark 2 is bolt in rock in rock outcrop between transects A3 and A4 on high bank. Elevation is 25.87 meters.
A1	Right	Rebar, 47 meters upstream from Sheeps Bridge.
A2	Left	Rebar, 47 meters upstream from transect A1.
A2	Right	Rebar, 47 meters upstream from transect A1.
A3	Left	Rebar about 45 meters upstream from transect A2.
A3	Right	Rebar, in bedrock 45 meters upstream from transect A2.
A4	Left	Rebar, 65 meters upstream from transect A3.
A4	Right	Bolt in bedrock, 65 meters upstream from transect A3.
A5	Left	Rebar, 56 meters upstream from transect A4.
A5	Right	Rebar, 56 meters upstream from transect A4.
A6	Left	Rebar, 139 meters upstream from transect A5.
A6	Right	Rebar, 139 meters upstream from transect A5.

Table 61. Habitat characteristics of reach A, Verde River below Tangle Creek, above Horseshoe Dam, Arizona, January 31, 1996 [Embeddedness categories: 2, 51 to 75 percent covered by fine sediment; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment; 5, less than 5 percent covered by fine sediment]

		Can	юру		Velocity		Sul		
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in Depth, in meters meters		Velocity, in meters per second	Dominant	Subdominant	Embeddedness
				Tra	nsect 1 (Riffle	e)			
46.9	133	156	18	3.5	¹ 0.67	0.82	Cobble	Boulder	5
				14.0	.46	1.20	Cobble	Gravel	5
				26.0	.18	.45	Cobble	Boulder	5
				Tr	ansect 2 (Run))			
45.3	175	149	25	5.0	1.88	.90	Cobble	Sand	4
				18.0	.29	.34	Cobble	Sand	4
				31.0	.27	.42	Cobble	Sand	4
				Tr	ansect 3 (Run))			
42.8	166	160	3	4.9	1.72	.40	Cobble	Sand	4
				22.0	.41	.32	Cobble	Sand	4
				34.0	.61	.46	Cobble	Sand	4
				Tr	ansect 4 (Run))			
32.3	167	156	15	9.2	1.85	.60	Cobble	Sand	3
				15.0	.83	.56	Cobble	Boulder	3
				21.0	.42	.28	Boulder	Cobble	2
				Tr	ansect 5 (Run))			
24.4	155	156	10	4.4	.79	.65	Boulder	Cobble	3
				8.8	1.98	.70	Cobble	Sand	3
				13.3	.78	.78	Cobble	Boulder	3
				Tra	nsect 6 (Riffle	e)			
31.6	109	157	13	5.8	1.65	1.01	Boulder	Cobble	2
				17.1	.47	.90	Boulder	Cobble	3
				25.3	.59	.47	Boulder	Cobble	3

¹Thalweg.




Figure 70. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, Verde River below Tangle Creek, above Horseshoe Dam, Arizona, based on measurements made January 31, 1996.




Figure 71. Bed-material types at transects 1–6 and average for reach A, Verde River below Tangle Creek, above Horseshoe Dam, Arizona, January 31, 1996.

Table 62. Density and dominance of woody vegetation for reach A, Verde River below Tangle Creek, above Horseshoe Dam, Arizona, January 31, 1996

[Length of reach, 355 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Fremont cottonwood (Populus fremontii)	13	0	8	3
Mesquite (Prosopis sp.)	380	8	8	3
Tamarisk (<i>Tamarix sp.</i>)	33	2	8	7
Willow (Salix sp.)	238	159	83	86






Figure 72. Location of transects 1–6, reach A, 91st Avenue wastewater-treatment plant outfall near Phoenix, Arizona.





Figure 73. Longitudinal profile, reach A, 91st Avenue wastewater-treatment plant outfall near Phoenix, Arizona, October 21 and 22, 1997. Local datum established using arbitrary elevation.

Table 63. Cross-sectional survey data for reach A, 91st Avenue wastewater-treatment plant outfall near Phoenix, Arizona, October 21 and 22, 1997

[All values are in meters. Distance is from left end point]

Trans	Transect A1		Transect A2		Transect A3		Transect A4		Transect A5		Transect A6	
Distance	Elevation											
0.0	29.4	0.0	29.1	0.0	30.4	0.0	30.4	0.0	30.1	0.0	30.8	
.9	28.9	.0	28.5	2.7	30.1	1.8	30.2	2.4	29.1	1.7	30.0	
.9	28.7	3.0	28.5	3.0	29.7	1.8	30.0	3.4	28.9	2.1	29.7	
1.7	28.7	5.2	28.4	4.3	29.5	3.0	29.8	4.3	28.8	4.6	29.5	
3.0	28.5	7.0	28.5	7.3	29.0	3.7	29.7	9.6	28.5	5.2	29.4	
6.7	28.3	9.8	28.8	11.0	29.0	5.5	29.6	10.7	28.3	6.9	29.2	
9.8	27.9	9.8	29.0	15.2	29.0	8.1	29.8	11.3	28.3	8.2	29.0	
11.6	27.7	14.0	29.0	19.2	28.9	11.6	30.0	13.4	28.2	10.1	29.2	
12.8	27.6	14.0	28.7	23.8	28.8	14.0	30.0	15.4	28.2	11.3	29.4	
14.3	27.5	16.2	28.5	25.6	28.8	15.2	30.0	16.3	28.3	11.7	29.6	
15.2	27.5	18.3	28.3	27.3	29.0	16.9	29.9	17.4	28.5	12.2	29.7	
15.5	27.7	20.1	28.8	27.4	29.4	19.2	30.0	18.6	28.8	15.2	30.4	
16.5	27.9	20.1	29.0	28.3	30.0	19.2	30.3	19.8	29.0	15.2	30.5	
17.1	28.3					22.7	30.9	19.8	29.7	16.2	31.2	
17.4	28.7							21.3	30.8			
17.8	29.2						_	22.7	31.0			







Figure 74A—F. Cross sections of channel, reach A, 91st Avenue wastewater-treatment plant outfall near Phoenix, Arizona, October 21 and 22, 1997. *A*, Transect A1. *B*, Transect A2. *C*, Transect A3. *D*, Transect A4. *E*, Transect A5. *F*, Transect A6. Local datum established using arbitrary elevation.

C. Transect A3



D. Transect A4





Figure 74A-F. Continued.






Figure 74A-F. Continued.

Table 64. Description and location of semipermanent monuments for reach A, 91st Avenue wastewater-treatment plant outfall, near Phoenix, Arizona, October 21 and 22, 1997

Transect	Туре	Description of location and reference marks						
RM-1	Brass tablet	Arizona Department of Transportation bench mark on downstream side of road crossing. Elevation, 30.48 meters.						
A1	Left	Rebar, 45 meters downstream from transect A2.						
A1	Right	Rebar, 45 meters downstream from transect A2.						
A2	Left	Rebar, 55 meters downstream from transect A3.						
A2	Right	Rebar, 55 meters downstream from transect A3.						
A3	Left	Rebar, 54 meters downstream from transect A4.						
A3	Right	Rebar, 54 meters downstream from transect A4.						
A4	Left	Rebar, 114 meters downstream from transect A5.						
A4	Right	Rebar, 114 meters downstream from transect A5.						
A5	Left	Rebar, 46 meters downstream from transect A6.						
A5	Right	Rebar, 46 meters downstream from transect A6.						
A6	Left	Rebar, 38 meters downstream from 91st Avenue.						
A6	Right	Rebar, 38 meters downstream from 91st Avenue.						

Table 65. Habitat characteristics of reach A, 91st Avenue wastewater-treatment plant outfall near Phoenix, Arizona, November 29, 1995 [Embeddedness categories: 0, no gravel, cobbles, or boulders present; 3, 26 to 50 percent covered by fine sediment; 4, 5 to 25 percent covered by fine sediment. Dashes indicate no data. <, less than]

		Canopy			Velocity		Sul		
Width of wetted channel, in meters	Aspect, in degrees	Angle of opening, in degrees	Density, in percent	Distance from left edge of water, in meters	Depth, in meters	Velocity, in meters per second	Dominant	Subdominant	Embeddedness
				Tran	sect 1 (Run)				
15.2	245	66	51	3.2	0.61	0	Gravel	Sand	4
				6.4	.76	<.01	Silt	Sand	0
				9.8	11.20	.30	Gravel		
				Tran	sect 2 (Run)				
18.6	254	149	18	2.1	.43	.94	Cobble	Gravel	4
				4.2	.53	1.02	Cobble	Gravel	4
				17.3	¹ .57	1.08	Gravel	Cobble	4
				Tran	sect 3 (Run)				
25.2	200	115	48	7.8	.19	1.09	Gravel	Cobble	3
				15.6	.36	.78	Cobble	Gravel	4
				23.4	¹ .65	.43	Gravel	Cobble	4
				Tran	sect 4 (Run)				
18.4	279	155	25	2.1	1.85	1.24			
				7.5	.40	.99			4
				Tran	sect 5 (Run)				
15.8	296	119	28	4.0	.18	.72	Cobble	Gravel	4
				8.0	.56	1.13	Cobble	Gravel	4
				12.2	¹ .69	1.20			
				Tran	sect 6 (Run)				
46.0	305	115	46	3.0	1.64	1.25	Cobble	Boulder	4

¹Thalweg.




Figure 75. Monthly distribution of solar insolation at transects 1, 6, and midreach, reach A, 91st Avenue wastewater-treatment plant outfall near Phoenix, Arizona, based on measurements made November 29, 1995.




Figure 76. Bed-material types at transects 1–6 and average for reach A, 91st Avenue wastewater-treatment plant outfall near Phoenix, Arizona, November 29, 1995.

Table 66. Density and dominance of woody vegetation for reach A, 91st Avenue wastewater-treatment plant outfall near Phoenix, Arizona, November 29, 1995

[Length of reach, 260 meters]

Species name	Mean basal area, in square centimeters	Dominance, in square centimeters	Absolute frequency, in percent	Relative density, in percent
Willow (Salix sp.)	804	531	50	32
Fremont cottonwood (Populus fremontii)	661	397	42	29
Tamarisk (<i>Tamarix sp.</i>)	28	12	42	21
Palo verde (Cercidium sp.)	23	5	17	11
Tree tobacco (Nicotiana glauca)	13	2	8	7